

Consento

(NAME & LOCATION) J. A. Glass, LP&S, Texas City

PLAINTIFF'S EXHIBIT

MON-897

DATE January 16, 1979 cc L. Chandler

SUBJECT PMSB Meeting Agenda for
Wednesday, January 17, 1979

REFERENCE

TO : G. W. Bostick J. A. Glass D. W. Metten
P. E. Brubaker R. A. Hernandez G. T. Ryan
J. E. Clark R. C. Martini J. G. Trafton
G. A. Danner M. L. Owens W. H. Triplett
G. W. Daues G. E. Small
W. C. Fuller C. M. McCullough

Following is the proposed agenda for the Plant Manager' Safety Board Meeting to be held in the Cafeteria Conference Room at 9:00 a.m. on January 17, 1979.

- ✓ 1. Review of Statistics -- J. A. Glass
2. Plant Manager's Comments
- ✓ 3. Old Business (from Minutes of PMSB Meeting, 12/20/78)
 - ✓ a. Emergency Procedure Manuals -- Glass
 - ✓ b. Plant-wide Alarm System Survey -- Triplett
 - b-1 January test of Emergency Procedure Plan--Alarm System
 - b-2 Cyanide Area Alarms
 - ✓ c. Respiratory Protection on Fit Testing -- Ryan
 - ✓ d. 1978 Safety and Property Protection Survey -- Glass
(PLEASE BRING YOUR COPY OF THE 1978 SURVEY REPORT)
4. Report of the Safety Advisory Committee (SAC) -- Ryan
 - a. Riding bicycles through operating units
 - b. Tech-Facts, No. 31, Control of Water Treatment Processes
 - c. Lighting Inside Tanks & Vessels (OSHA requires 12V)
 - d. Tank Content Signs
 - e. Other (Ladder procedure) GFI not accepted by OSHA
- 20,000 hr on bicycles
SAC
6/6/81
p. 14
5. Report of Safety and Housekeeping Action Committee (SHAC) -- Triplett/Hernandez
 - a. Fire & Entry Permit Procedure
 - b. Plant Breathing Analyzer
 - c. Procedure for Using Hoses within the Plant
 - d. Other
6. Review of Incidents (Reports Not Yet Issued)
 - a. Fire in Polyethylene Mixer Area (35F) * 2 Extra
 - b. Owens-Corning Insulator Incident (Dept. 53)
 - c. Recordable Injury to Boilermaker/Laceration to knee
 - d. Muriatic Acid Spill (Dept. 13)
 - e. Benzene Tank Overflow (Dept. 13)
 - f. Condensate Tank Floating Roof-Drain Valve Failure (Dept. 10)

SC 17465

LAM025719

7. Other Significant Events

- a) Decatur Fire Report -- Glass
- b) Seal Sands Steam Line Failure

8. Contractor Safety -- McCullough

9. Other Items

- a) Metten will review removing unneeded pipes from pipe rack.



J. A. Glass

JAG/jge

SC 17466

LAM025720