

# WORK CHECK LIST FOR

GAS OIL UNIT 5/70

SHEET 3

SHUTDOWN

| CHARGE<br>NUMBER | JOB NO. | ORIGIN |       |       | PRIORITY | EQUIP<br>NO.                                 | WORK DESCRIPTION                                                                                                                                                                                                         | ASSIGNED TO | OK'D |       |  |  |  |  |  |  |
|------------------|---------|--------|-------|-------|----------|----------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------|-------|--|--|--|--|--|--|
|                  |         | OPR.   | INSP. | ENGR. |          |                                              |                                                                                                                                                                                                                          |             | OPR. | ENGR. |  |  |  |  |  |  |
| 49262<br>-001    |         |        |       |       |          |                                              | 'C'-COLUMNS CONTINUED                                                                                                                                                                                                    |             |      |       |  |  |  |  |  |  |
|                  | 20      | X      | X     |       |          |                                              | TRAY 12 - RAISE BOWED-UP SECTIONS NORTH HALF OF TRAY; REMOVE & STRAIGHTEN SOUTH HALF OF TRAY SECTIONS; STRAIGHTEN BOWED DOWN CORNERS; REPLACE ASBESTOS GASKETING, REPLACE MISSING TRAY HOLDOWN MEMBERS & RE-SECURE TRAY. |             |      |       |  |  |  |  |  |  |
|                  | 21      | X      | X     |       |          |                                              | TRAY 13 - RAISE BOWED-UP SECTIONS OF TRAY, REPLACE ASBESTOS GASKETING, REPLACE MISSING HOLDOWN MEMBERS & RE-SECURE TRAY.                                                                                                 |             |      |       |  |  |  |  |  |  |
|                  | 22      | X      | X     |       |          |                                              | TRAY 14 - RAISE BOWED-UP SECTIONS OF TRAY, REPLACE ASBESTOS GASKETING, REPLACE MISSING HOLDOWN MEMBERS & RE-SECURE TRAY.                                                                                                 |             |      |       |  |  |  |  |  |  |
|                  | 23      | X      | X     |       |          |                                              | REPLACE MISSING KORN WARE ASSEMBLIES TRAYS 12 THRU 15 PER INSPECTOR & DLR W/R 22-040                                                                                                                                     |             |      |       |  |  |  |  |  |  |
|                  | 24      | X      | X     |       |          |                                              | TRAYS 16 & 17 - REPLACE TRAYS, TRAY SUPPORT RINGS, DOWNCOMERS & DRAW BOX BELOW TRAY 17. PER DLR W/R 22-040                                                                                                               |             |      |       |  |  |  |  |  |  |
|                  | 25      | X      | X     |       |          |                                              | STRIP LINE SHELL FROM JUST ABOVE TRAY 15 UP TO JUST BELOW TRAY 18, USING TYPE 410 S.S. MATERIAL. PER DLR W/R 22-040                                                                                                      |             |      |       |  |  |  |  |  |  |
|                  | 26      | X      | X     |       |          |                                              | TRAY 18 - REPLACE ALL CORRODED BUBBLE CAP BOLTS PER INSPECTOR INSTRUCTIONS.                                                                                                                                              |             |      |       |  |  |  |  |  |  |
|                  | 27      | X      | X     |       |          |                                              | TRAY 19 & 20 - TIGHTEN LOOSE BUBBLE CAPS. REPLACE APPROX 10 CAPS (EACH TRAY) PER INSPECTOR.                                                                                                                              |             |      |       |  |  |  |  |  |  |
|                  | 28      | X      | X     |       |          |                                              | REPAIR OR REPLACE ALL RAMS HORNS PER INSPECTOR INSTRUCTIONS. NOTE: THERE IS A POSSIBILITY ALL RAMS HORNS WILL BE REPLACED USING ALLOY MATERIAL PER DLR W/R 22-040                                                        |             |      |       |  |  |  |  |  |  |
| 29               |         |        |       |       |          | C2203 1/2 S STRIPPER, TRY WITHIN 5/10 ON RUN |                                                                                                                                                                                                                          |             |      |       |  |  |  |  |  |  |

CHEV B8 5757