

A U T O M O T I V E D A T A B O O K B U L L E T I N #3-921

January 27, 1993

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>			
1993, Legend	7382-D503**	D/D	7418-D536**
<u>AUDI</u>			
1993, 90 Quattro	7306-D419**	D/D	7309-D228**
1992-91, 80, 90 Quattro	7143-D290**	D/D	7309-D228**
OR	7306-D419**	D/	
1992, 80, 90	7143-D290**	D/D	7144-D228**
1993, 100	7434-D555**	D/D	7309-D228**
1992, 100	7434-D555**	D/D	7144-D228**
1993-92, 100 Quattro	7434-D555**	D/D	7309-D228**
OR	7306-D419**	D/	
1993-92, V8 Quattro	7346-D467**	D/D	7309-D228**
OR	7306-D419**	D/	
1991, V8 Quattro	7346-D467**	D/D	7309-D228**
OR	7306-D419**	D/	
<u>BMW</u>			
1993, 525i	7284-D394**	D/D	7286-D396**
1993-89, 535i	7284-D394**	D/D	7286-D396**
1993, M-5	7284-D394**	D/D	7286-D396**
1993, 740i	7284-D394**	D/D	7286-D396**
1993, 740iL	7284-D394**	D/D	7286-D396**
1993, 750iL	7284-D394**	D/D	7286-D396**
1993, 850i	7426-D547**	D/D	7427-D548**
<u>CADILLAC (See Corrections)</u>			
1993, Brougham	7214A-D52	D/	
<u>CHEVROLET TRUCK</u>			
W5 Series 1992-91	1458-S672 (Notes #12 & 30)	N/N	1455-S669
<u>DODGE (See Comments)</u>			
1993, Colt 4DR		/D	7474-D596** (Notes #5 & 23)
1993, Stealth	7412-D530**	D/D	7272-D383**
1993, Stealth 4WD	7413-D531**	D/D	7414-D532**
1993-92, Viper	7471-D592** (Notes #2 & 19)	D/D	7472-D491** (Note #3)
<u>DODGE TRUCK (See Comments)</u>			
1993, Dakota	7410A-D593 (Notes #1 & 20)	D/BH	2168T-538
OR		/BH	2089T-445*

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright® by Friction Materials Standards Institute, Inc.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>EAGLE</u>				
1993, Summit 4DR			/D	7474-D596**
<u>FORD (See Comments & Corrections)</u>				
1993, Crown Victoria		7378B-D499	D/D	7424A-D544
1993, Crown Victoria Police		7082B-D346	D/D	7424A-D544
1993, Escort		7219-D466**	D/N	1407-598*
	OR	7353-D473**	D/D	7338-D458
1993, Mustang 2.3L		7072B-D310	D/BH	2151T-569*
1993, Mustang GT 5.0L		7379A-D431	D/BH	2151T-569*
	OR		/D	7239A-D347
1993, Taurus		7308A-D421	D/N	1395-566
1993, Taurus Wagon		7308A-D421	D/N	1396-S618
1993, Thunderbird Super Coupe		7478-D600**	D/D	7477A-D599
		(Notes #9 & 27)		(Notes #8 & 26)
<u>GMC TRUCK</u>				
W5 Series	1992-91	1458-S672	N/N	1455-S669
<u>HINO</u>				
FB 14	1989	1459	TF/TF	1459
		(Note #13)		
SF 17	1991-89		/A	1460
				(Note #14)
SG 19	1991-89			1460
SG 23	1991-89			1460
SG 20	1992			1460
SG 23	1992			1460
<u>ISUZU (Commercial)</u>				
NRR	1992-91	1458-S672	N/N	1455-S669
<u>LINCOLN</u>				
1993, Continental		7479-D601**	D/	
		(Notes #10 & 28)		
1992-90, Continental		7308A-D421	D/D	7269A-D545
	OR	7475-D597**	D/	
		(Notes #6 & 24)		
1993, Mark VIII		7476-D598**	D/D	7477A-D599
		(Notes #7 & 25)		
1993, Town Car		7378B-D499	D/D	7424A-D544
<u>MERCURY (See Comments)</u>				
1993, Cougar XR7		7478-D600**	D/D	7477A-D599
1993, Grand Marquis		7378B-D499	D/D	7424A-D544
1993, Grand Marquis Police		7082B-D346	D/D	7424A-D544
1993, Sable		7308A-D421	D/N	1395-566
1993, Sable Wagon		7308A-D421	D/N	1396-S618
1993, Tracer		7219-D466**	D/N	1407-598
	OR	7353-D473**	D/D	7338-D458
<u>MITSUBISHI</u>				
1993, Mirage			/D	7474-D596**
<u>NISSAN</u>				
1993, Altima		7407-D526**	D/N	1457-S671*
				(Notes #11 & 29)
	OR		/D	7421-D540**
1993, Maxima			/D	7421-D595**
				(Note #22)

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>PLYMOUTH</u>			
1993, Colt 4DR		/D	7474-D596**
<u>PORSCHE</u>			
1993, 928 GTS	7473-D594** (Notes #4 & 21)	D/	
<u>ROCKWELL AXLE</u>			
15 dd 8 5/8 Q-Plus	4710 (Note #17)	A	
16 1/2 dd 8 5/8 Q-Plus	4711 (Note #18)	A	
<u>SUZUKI</u>			
1993, Swift	7331-D451** OR	D/N /N	1414-608* 1461-S674* (Notes #15 & 32)
1993, Swift GT, GTI	7332-D452**	D/D	7180-D277**
1993, Swift 4DR		/N	1461-S674*
1993, Samurai	7250-D444**	D/N	1408-600*

EMERGENCY AND PARKING BRAKE LINING SIZESMITSUBISHI

1992, Expo LRV 4WD (DIH)

REAR
FMSI NO.2175-S673
(Notes #16 & 31)C O M M E N T S

1992-89 Taurus and Sable Sedan and Wagon used 7308A-D421 with 39.5mm dia. rose clip on inner shoes. 1993 Taurus and Sable Sedan and Wagon use 7308A-D421 with 58.1mm dia. rose clip on inner shoes.

1993 Dodge Dakota Front FMS 7410A-D593:
2WD Outer shoe does not have anti-rattle clip.
4WD Outer shoe has anti-rattle clip.

Existing lining used with new shoe:

Lining	Assembly	Application
7421	7421-D595	1993 Nissan Maxima Rear

Existing shoe with new lining:

Shoe	Assembly	Application
D491	7472-D491	1993-92 Dodge Viper Rear

C O R R E C T I O N S

Bulletin #2-921 incorrectly listed 7384-D505 for the front application of the 1993 Cadillac Brougham. The correct listing is 7214A-D52.

Bulletin #1-921 incorrectly listed 1993 Ford Mustang 2.3L front disc as 7072B-D237. The correct listing is 7072B-D310.

Bulletin #1-921 incorrectly listed 1993 Ford Thunderbird Super Coupe with 7304A-D417 front and 7239A-D545 rear. The correct listing is 7478-D600 front and 7477A-D599 rear.

DISC BRAKE LINING ASSIGNMENTS

Note #1	FMSI 7410A	7410A-D593
	46.5 x 12.1 x 122.0	4 - 32
	(1.83 x .475 x 4.80)	

DISC BRAKE LINING ASSIGNMENTS (con't)

Note #2	<u>FMSI 7471</u> 50.8 x 16.9 x 109.7 (2.00 x .665 x 4.32)	7471-D592 4 IM
Note #3	<u>FMSI 7472</u> 40.4 x 14.8 x 92.5 (1.59 x .583 x 3.64)	7472-D491 4 IM
Note #4	<u>FMSI 7473</u> 60.5 x 16.5 x 129.0 (2.38 x .650 x 5.08)	7473-D594 4 IM
Note #5	<u>FMSI 7474</u> 35.0 x 14.5 x 81.5 (1.38 x .570 x 3.21)	7474-D596 4 IM
Note #6	<u>FMSI 7475</u> 45.0 x 15.6 x 144.0 45.0 x 15.6 x 144.0 (1.77 x .614 x 5.67) (1.77 x .614 x 5.67)	7475-D597 2 IM 2
Note #7	<u>FMSI 7476</u> 55.1 x 17.5 x 117.9 (2.17 x .689 x 4.64)	7476-D598 4 IM
Note #8	<u>FMSI 7477A</u> 35.2 x 11.0 x 99.3 (1.39 x .435 x 3.91)	7477A-D599 4 - 20
Note #9	<u>FMSI 7478</u> 51.2 x 17.2 x 113.1 (2.02 x .677 x 4.45)	7478-D600 4 IM
Note #10	<u>FMSI 7479</u> 50.5 x 17.5 x 117.9 (1.99 x .689 x 4.64)	7479-D601 4 IM

DRUM BRAKE LINING ASSIGNMENTS

Note #11	<u>FMSI 1457</u> 228.6dd - 35.0 x 4.1 x 219.0 (9.00 - 1.38 x .161 x 8.62)	1457-S671 4 Bonded
Note #12	<u>FMSI 1458</u> 320.0dd - 109.7 x 11.5 x 336.0 (12.60 - 4.32 x .453 x 13.23)	1458-S672 4 - 56
Note #13	<u>FMSI 1459</u> 320.0dd - 75.0 x 8.2 x 323.0 (12.60 - 2.95 x .325 x 12.72)	1459 4 - 40
Note #14	<u>FMSI 1460</u> 16.0 - 7.00 x .600 x 8.25	1460 8 - 96

DRUM BRAKE LINING ASSIGNMENTS (con't)

Note #15	<u>FMSI 1461</u>	1461-S674
	200.0dd - 30.0 x 4.4 x 192.0	4 Bonded
	(7.87 - 1.18 x .173 x 7.50)	
Note #16	<u>FMSI 2175</u>	2175-S673
	170.0dd - 30.0 x 2.8 x 148.0	4 Bonded
	(6.69 - 1.18 x .110 x 5.83)	

BRAKE BLOCK LINING ASSIGNMENTS

Note #17	<u>FMSI 4710</u>	
	15.00dd - 8.63 x .750 x 7.69	4 1/4R 128
	Tapered x 7.44	4
Note #18	<u>FMSI 4711</u>	
	16.50dd - 8.63 x .875 x 8.42	4 1/4R 112
	Tapered x 8.23	4

DISC BRAKE SHOE ASSIGNMENTS

Note #19	<u>FMS D592</u>	7471-D592	Dodge
	109.7 x 5.1		
	(4.32 x .201)		
Note #20	<u>FMS D593</u>	7410A-D593	Dodge Truck
	177.3 x 5.5		
	(6.98 x .217)		
Note #21	<u>FMS D594</u>	7473-D594	Porsche
	131.8 x 5.1		
	(5.19 x .201)		
Note #22	<u>FMS D595</u>	7421-D595	Nissan
	105.4 x 6.5		
	(4.15 x .256)		
Note #23	<u>FMS D596</u>	7474-D596	Dodge Eagle Mitsubishi Plymouth
	98.8 x 5.1		
	(3.89 x .201)		
Note #24	<u>FMS D597</u>	7475-D597	Lincoln
	188.0 x 6.0		
	188.0 x 6.0		
	(7.40 x .236)		
	(7.40 x .236)		
Note #25	<u>FMS D598</u>	7476-D598	Lincoln
	124.0 x 6.1		
	(4.88 x .240)		
Note #26	<u>FMS D599</u>	7477A-D599	Ford Lincoln Mercury
	114.3 x 5.8		
	(4.50 x .228)		
Note #27	<u>FMS D600</u>	7478-D600	Ford Mercury
	136.6 x 6.4		
	(5.38 x .252)		

DISC BRAKE SHOE ASSIGNMENTS (con't)

Note #28	<u>FMS D601</u>	7479-D601	Lincoln
	124.0 x 6.6		
	(4.88 x .260)		

DRUM BRAKE SHOE ASSIGNMENTS

Note #29	<u>FMS S671</u>	1457-S671	Nissan
	228.6 x 35.0		
	(9.00 x 1.38)		
Note #30	<u>FMS S672</u>	1458-S672	Isuzu (Commercial)
	320.0 x 110.0		
	(12.60 x 4.33)		
Note #31	<u>FMS S673</u>	2175-S673	Mitsubishi
	170.0 x 30.0		
	(6.69 x 1.18)		
Note #32	<u>FMS S674</u>	1461-S674	Suzuki
	200.0 x 30.0		
	(7.87 x 1.18)		

CLUTCH FACING APPLICATIONS BY MODELFORD TRUCK

1989-83, Ford Truck	8052
	(Note #33)

NISSAN

1990-86, Nissan Pick-up	9040
	(Note #34)
1990-87, Nissan Pathfinder	9040

CLUTCH FACING ASSIGNMENTS

Note #33	<u>FMSI 8052</u>			
	8.48 x 6.09 x .138	16 Gr A Str	-	16
Note #34	<u>FMSI 9040</u>			
	9.465 x 5.92 x .140	16 Gr A Str	-	16

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.