

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	06/10/2022	Time	12:30
Inspection Due	2016-06-19T00:00:00Z	Operator Representative	Terminated Lease		
Operator Info	Terminated Lease	Inventory ID	OS5581000		
		API Well No			
	, Phone:	Lease Name	Reed		
		Well ID	19		
Location	NW 26 22N 10E	Status	Inactive	Well Type	Disposal
Latitude	36.356227	Longitude	-96.209412		
Inspection Reason	Plugging Witnessed		Responsible Company at Time of Inspection		
Inspect No.		Date Last MIT	01/20/2004	Last Test Result	Fail
Casing	4	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 460
FLM Canister Pressure		Actual Pressure			Max Volume 600
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	I observed the bottom cement plug placement on the Reed No. 19 well (OS5581000). The workover rig ran in the well with tubing to 1,267.5 feet and pumped 5 sacks of gel and 15 barrels of water to load the hole. P&P cement company pumped 32 sacks of cement beginning at 1,267.5 feet. The top plug placement was scheduled to take place 06/13/2022. The Reed 19 well was abandoned at the time of plugging. The plugging operation was led by the Osage Minerals Council.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.356281, -96.209349		
City: Skiatook	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0604

Orientation: NW

Date of Photo: 06/10/2022

Time of Photo: 12:36 PM

Latitude: 36.356281

Longitude: -96.209349

Photographer: Matthew Allen

Description: This was the Reed No. 19 well. At the time of inspection/plugging, the Reed 19 well (OS5581000) was abandoned and located on a terminated lease. The Osage Minerals Council led the plugging operation. A workover rig and cement pumping truck were both on location at the time of the plugging operation.