

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
2-17-00	3408	5	10.0	E. unloading Mid. station			cleared @ 0930. no contact w/ yard			
0220	BM	2								
2-17-00	3409	New Unit	8.7	Middle VCM Receiver	10	NR	see leak # 3412	2-18	PN	PN
2135	CN	#8								
2-17-00	3410	New Unit	10.0	Middle VCM Receiver	10	NR	see leak # 3412	2-18	PN	PN
2205	CN	#8								
2-17-00	3411	New Unit	10.0	Middle VCM Receiver	15	NR	see leak # 3412	2-18 2-18	PN	PN
2240	CN	#8								
2-17-00	3412	New Unit	8.2	Middle VCM Receiver	yes	no	repaired tubing on WESTPUM receiver pressure transmitter.	2-18-00	PN	PN
2255	CN	#8								
2-18-00	3413	#9	5.7	BOTTOM OF HIGH MOLE STRIPPER	NO	NO	NO leak Found	NA	NA	NA
21:11	AS									

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.

This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.