

A U T O M O T I V E D A T A B O O K B U L L E T I N #1-941
August 11, 1994

This is the first Automotive Data Book Bulletin since the copy was sent to the printer for the 1994 Automotive Data Book Catalog.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>BUICK</u>			
1995, Riviera	7384-D623**	D/D	7387-D508**
<u>CHEVROLET</u>			
1995, Impala SS	7492-D614**	D/D	7505-D628**
1995, Lumina	7265-D376**	D/N	1394-S636
<u>CHEVROLET TRUCK/GMC TRUCK</u>			
C 3500 1994	7081-D149**	D/D	7081-D149**
K 3500 1994	7081-D149**	D/D	7081-D149**
<u>FORD</u>			
1995, Contour	7528-D648** (Notes #9 & #18)	D/N	1479-S696* (Notes #11 & #23)
1994, Mustang Cobra 5.0L	7300-D412**	D/D	7524-D627** (Note #5)
<u>FORD TRUCK</u>			
Windstar 1995	7479-D601**	D/N	1452-S665
<u>HONDA</u>			
1994, Passport	7347-D363**	D/N	1360-S619*
OR	7459-D579**	D/D	7460-D580**
<u>HYUNDAI (See Comments & Corrections)</u>			
1994, Elantra	7329-D449**	D/N	1448-S693* (Note #20)
OR		/D	7344-D464**
1993(late), Elantra	7329-D449**	D/N	1448-S693*
1993(early)-92, Elantra	7329-D449**	D/N	1448-S661*
1994, Excel	7376-D497**	D/	
1994-93(late), Scoupe	7293-D440**	D/N	1451-S694 (Note #21)
1994-93(late), Sonata	7329-D449**	D/N	1395-599*
OR		/D	7236-D342**
<u>MAZDA (See Comments)</u>			
1995, Millenia	7520-D643** (Notes #1 & #13)	D/D	7521-D553** (Note #2)
1994, MPV	7430-D551**	D/D	7432-D553**
1994, MPV 4x4		/D	7432-D553**
<u>MERCEDES (See Comments)</u>			
1994, C220	7523-D645** (Notes #4 & #15)	D/D	7315-D335**
1994, C280	7523-D645**	D/D	7315-D335**
OR		/D	7496-D620**
1994, E500	7525-D561** (Note #6)	D/D	7374-D495**

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright® by Friction Materials Standards Institute, Inc.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>MERCEDES (con't)</u>			
1994, SL320	7525-D561**	D/D	7374-D495**
1994, SL500	7525-D561**	D/D	7374-D495**
1994, SL600	7525-D561**	D/D	7484-D603**
1994, E320	7525-D561**	D/D	7374-D495**
1994, E420	7525-D561**	D/D	7374-D495**
1993, 300E	7525-D561**	D/D	7374-D495**
1993, 300TE	7525-D561**	D/D	7374-D495**
1993, 400E	7525-D561**	D/D	7374-D495**
1993-92, 500E	7525-D561**	D/D	7374-D495**
1993-90, 300CE	7525-D561**	D/D	7374-D495**
1993-90, 300SL	7525-D561**	D/D	7374-D495**
1993-90, 500SL	7525-D561**	D/D	7374-D495**
1994, S320	7525-D561**	D/D	7526-D603** (Note #7)
	OR 7457-D577**	D/	
1994, S350TD	7457-D577**	D/D	7526-D603**
1993-92, 300SE		/D	7526-D603**
1993-92, 300STD		/D	7526-D603**
1994, S420	7525-D561**	D/D	7484-D603**
	OR 7457-D577**	D/	
1994, S500	7525-D561**	D/D	7484-D603**
	OR 7457-D577**	D/	
1994, S600	7457-D577**	D/D	7484-D603**
1993-90, 190E	7367-D487**	D/D	7314-D426**
1989, 260E	7311-D423**	D/D	7315-D335**
1993-90, 300D	7311-D423**	D/D	7315-D335**
1992-90, 300TE	7311-D423**	D/D	7374-D495**
1988, 300TD	7311-D423**	D/D	7316-D427**
1991, 350SDL	7111-D145**	D/D	736-D31**
1991-90, 350SD	7111-D145**	D/D	736-D31**
1993, 400SE	7457-D577**	D/D	7484-D603**
1991, 400SEL	7111-D145**	D/D	736-D31**
1988-86, 400SEL	7111-D145**	D/D	736-D31**
1993, 500SEC	7457-D577**	D/D	7484-D603**
1993, 500SEL	7457-D577**	D/D	7484-D603**
1991, 560SEC	7111-D145**	D/D	736-D31**
1989-88, 560SEC	7111-D145**	D/D	736-D31**
1991-86, 560SEL	7111-D145**	D/D	736-D31**
1989, 560SL	7312-D424**	D/D	736-D31**
<u>MERCURY</u>			
1995, Mystique	7528-D648**	D/N	1479-S696*
<u>NISSAN</u>			
1994, 300ZX	7340-D647** (Note #17)	D/D	7341-D461**
<u>OLDSMOBILE</u>			
1995, Aurora	7384-D623**	D/D	7387-D508**
<u>SAAB</u>			
1994, 900	7522-D644** (Notes #3 & #14)	D/D	7316-D427**
<u>SUBARU</u>			
1994, Impreza	7442-D563**	D/N	1462-S676*
	OR 7350-D470**	D/D	7351-D471**
<u>THEURER TRAILER (See Corrections)</u>			
420 x 180		/A	1477TT

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>TOYOTA</u>			
1994, Camry	7357-D476**	D/	
<u>UD (Nissan Commercial)</u>			
1994, 1400	7527-D646** (Notes #8 & #16)	D/N	1478-S695 (Notes #10 & #22)
GMC Truck	<u>PARKING BRAKE</u>	2079-S692* (Notes #12 & #19)	

C O M M E N T SExisting lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
1448	1448-S693	1994-93(late) Hyundai Elantra Rear
1451	1451-S694	1994-93(late) Hyundai Scoupe Rear
7340	7340-D647	1994 Nissan 300ZX Front

Existing shoe with new lining:

<u>Shoe</u>	<u>Assembly</u>	<u>Application</u>
D553	7521-D553	1995 Mazda Millenia Rear
D561	7525-D561	1994 Mercedes E500, SL320, SL500, SL600, E320, E420 Front
		1993 Mercedes 300E, 300TE, 400E Front
		1993-90 Mercedes 300SL, 500SL, Front
		1993-92 Mercedes 500E
D603	7526-D603	1994 Mercedes S320, S350TD Rear
		1993-92 Mercedes 300SE, 300STD Rear
D627	7524-D627	1994 Ford Mustang Cobra 5.0L Rear

C O R R E C T I O N S

FMSI 1477TT was originally issued in error as 1477. Since the segments are tapered the TT suffix is correct.

1994-93 Hyundai Scoupe has FMS 1451-S663 cataloged for rear application. The correct application for 1994-93(late) Hyundai Scoupe Rear is 1451-S694.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7520</u>	7520-D643
	51.6 x 16.1 x 123.2	4 IM
	(2.03 x .634 x 4.85)	
Note #2	<u>FMSI 7521</u>	7521-D553
	35.0 x 15.0 x 98.8	2 IM
	35.0 x 14.0 x 98.8	2
	(1.38 x .591 x 3.89)	
	(1.38 x .551 x 3.89)	
Note #3	<u>FMSI 7522</u>	7522-D644
	46.2 x 17.1 x 113.5	2 IM
	46.2 x 16.9 x 113.5	2
	(1.82 x .673 x 4.47)	
	(1.82 x .665 x 4.47)	
Note #4	<u>FMSI 7523</u>	7523-D645
	52.6 x 19.3 x 106.2	4 IM
	(2.07 x .760 x 4.18)	
Note #5	<u>FMSI 7524</u>	7524-D627
	32.0 x 15.0 x 72.6	4 IM
	(1.26 x .591 x 2.86)	

DISC BRAKE LINING ASSIGNMENTS (con't)

Note #6	<u>FMSI 7525</u> 57.7 x 15.2 x 99.8 (2.27 x .600 x 3.93)	7525-D561 4 IM
Note #7	<u>FMSI 7526</u> 49.5 x 15.2 x 61.7 (1.95 x .600 x 2.43)	7526-D603 4 IM
Note #8	<u>FMSI 7527</u> 55.4 x 19.9 x 160.5 (2.18 x .782 x 6.32)	7527-D646 4 IM
Note #9	<u>FMSI 7528</u> 48.3 x 18.4 x 117.9 48.3 x 17.8 x 117.9 (1.90 x .724 x 4.64) (1.90 x .701 x 4.64)	7528-D648 2 IM 2
<u>DRUM BRAKE LINING ASSIGNMENTS</u>		
Note #10	<u>FMSI 1478</u> 320.0dd - 90.0 x 7.6 x 334.0 (12.60 - 3.54 x .300 x 13.15)	1478-S695 4 - 48
Note #11	<u>FMSI 1479</u> 203.2dd - 36.0 x 6.6 x 195.6 203.2 - 36.0 x 3.7 x 195.6 (8.00 - 1.42 x .260 x 7.70) (8.00 - 1.42 x .146 x 7.70)	1479-S696 2 Bonded 2 Bonded
Note #12	<u>FMSI 2079</u> 12.00 - 3.00 x .250 x 13.88	2079-S692 Bonded
<u>DISC BRAKE SHOE ASSIGNMENTS</u>		
Note #13	<u>FMS D643</u> 142.0 x 6.1 (5.59 x .240)	7520-D643 Mazda
Note #14	<u>FMS D644</u> 155.2 x 5.6 156.5 x 5.6 (6.11 x .220) (6.16 x .220)	7522-D644 Saab
Note #15	<u>FMS D645</u> 108.0 x 5.6 (4.25 x .220)	7523-D645 Mercedes
Note #16	<u>FMS D646</u> 177.0 x 6.1 (6.97 x .240)	7527-D646 UD
Note #17	<u>FMS D647</u> 119.2 x 4.6 (4.69 x .181)	7340-D647 Nissan
Note #18	<u>FMS D648</u> 155.2 x 5.6 156.5 x 5.1 (6.11 x .220) (6.16 x .201)	7528-D648 Ford Mercury

DRUM BRAKE SHOE ASSIGNMENTS

Note #19	<u>FMS S692</u> 12.00 x 3.00	2079-S692	GMC Truck
Note #20	<u>FMS S693</u> 203.2 x 38.5 (8.00 x 1.52)	1448-S693	Hyundai
Note #21	<u>FMS S694</u> 180.0 x 35.0 (7.09 x 1.38)	1451-S694	Hyundai
Note #22	<u>FMS S695</u> 320.0 x 90.0 (12.60 x 3.54)	1478-S695	UD
Note #23	<u>FMS S696</u> 203.2 x 36.0 (8.00 x 1.42)	1479-S696	Ford Mercury

CLUTCH FACING APPLICATIONS BY MODELCHEVROLET TRUCK

7.0L	11004B (Note #30)
1987-84	10024A (Note #29)
1988-87	11022 (Note #32)

FORD

1987-93, Mustang 5.0L	10023 (Note #27)
-----------------------	---------------------

FORD TRUCK

7.0L & 6.9L Diesel	11004C (Note #31)
--------------------	----------------------

GMC TRUCK

1987-84	10024A
1988-87	11022

ISUZU TRUCK

1985-87, 3.9L Turbo Diesel	10024 (Note #28)
1987-84	10024A
1988-87	11022
1984-88 5.8L Turbo	13001 (Note #34)

MASSEY FERGUSON

Massey Ferguson Tractor	11023 (Note #33)
-------------------------	---------------------

NISSAN

1989-92, Axxess 2.4L	9056 (Note #26)
1985-93, D21 Pick-Up 2.4L	9056
1986-89, Pathfinder 2.4L	9056
1987-90, 300ZX Turbo	9041B (Note #25)
1986-89, D21 Pick-Up 3.0L	9041B
1987-89, Pathfinder	9041B

TOYOTA

1970-79, Corolla

785B

(Note #24)

1971-73, Carina

785B

1980-89, Tercel

785B

CLUTCH FACING ASSIGNMENTS

Note #24	<u>FMSI 785B</u> 7.52 x 5.20 x .138	18 Gr A Str	-	18
Note #25	<u>FMSI 9041B</u> 9.43 x 6.31 x .135	16 Gr A Str	-	16
Note #26	<u>FMSI 9056</u> 9.45 x 5.63 x .138	16 Gr A Str	-	16
Note #27	<u>FMSI 10023</u> 10.40 x 6.50 x .145	40 DGAP	-	40
Note #28	<u>FMSI 10024</u> 10.80 x 7.15 x .130	36 DGAP	-	36
Note #29	<u>FMSI 10024A</u> 10.82 x 7.16 x .128	36 DGAP	-	36
Note #30	<u>FMSI 11004B</u> 11.88 x 6.75 x .140	40 DGEP	-	40
Note #31	<u>FMSI 11004C</u> 11.88 x 6.75 x .140	40 DGAP	-	40
Note #32	<u>FMSI 11022</u> 11.74 x 7.58 x .157	36 DGAP	-	36
Note #33	<u>FMSI 11023</u> 11.88 x 7.39 x .156	40 DGAP	-	40
Note #34	<u>FMSI 13001</u> 13.75 x 8.75 x .187	36 DGAP	-	36

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.