

FILE NAME: Allied Signal Bendix (ASB)

DATE: 1991 June 24

DOC#: ASB096

DOCUMENT DESCRIPTION: Letter from Rayloc to Bendix RE Asbestos Dust Concerns



DIVISION OF GENUINE PARTS COMPANY
600 RAYLOC DRIVE, S.W.
P.O. BOX 43146
ATLANTA, GEORGIA 30378
PHONE 404 / 691-3780

June 24, 1991

Ms. Sheri Muncey
Bendix Friction Material Div.
Allied Signal
P O Box 2610
Cleveland, TN 37320-2610

Dear Ms. Muncey:

As the pressure and awareness of the problems with asbestos continue to grow, more controls must be initiated to comply with the requirements of the environmental agencies.

Your company has been advised in the past about our concerns with the dust in your packages. Some improvements have been made but it is imperative that we eliminate this potential hazard.

Our policy for all future shipments will be to inspect your product and package for dust. If dirt is prevalent, we will reject the shipment and return it, freight collect, for your rework. All purchase orders will reflect the requirement for "dust free parts and cartons".

Your immediate attention to this problem and a written response outlining your corrective action is anticipated and appreciated. If we can provide additional information, please advise.

Sincerely,


RAYLOC

A handwritten signature in cursive script that reads "Jack Hughes".

Jack Hughes
Purchasing/Inventory
Control Manager

JH:jw

cc: Joe White
Tom Daniel
Henry Dunn
John George
Cherry Barker



HWMURPHY11210