



A

Interoffice Communication

To A. H. Sather
From J. V. Uptain
Date August 21, 1979
Subject VCM DOSIMETRY - JULY, 1979

Following are the results of VCM dosimetry during July, 1979. 63 samples were taken, 6 of which indicated overexposure.

<u>Range, PPM</u>	<u>No. Samples</u>	<u>%</u>
0.0 - 0.5	52	82.54
0.5 - 1.0	5	7.94
1.0 - 5.0	6	9.52
5.0+	0	0.00
	<u>63</u>	<u>100.00</u>

The results of the 6 overexposures are shown in Table I.

Jerald Uptain

jf

Attachment

c: D. A. Kuhn, J. J. Hall, O. D. Steffey

VAB.0001041329

TABLE I
VCM OVEREXPOSURES FOR JULY, 1979

<u>Date</u>	<u>Job Classification</u>	<u>8-Hour TWA Overexposure, PPM</u>	<u>Cause</u>
7/5	Maintenance Supervisor	1.0	Specific cause not found.
7/14	Vinyl Lead Operator	1.7	Specific cause not found. Worked in control room entire period.
7/13	Maintenance Mechanic	1.7*	Repaired VCM charge lines.
7/17	Maintenance Mechanic	1.3	Specific cause not found.
7/18	Maintenance Mechanic	3.7*	Blanked VCM charge pump.
7/27	Maintenance Mechanic	1.0	Specific cause not found.

* Respiratory equipment was worn.