

F. Schuttenthal



Ford Parts and Service Division
Ford Motor Company

P.O. Box 3000
Livonia, Michigan 48151

November 7, 1986

Mr. E. L. Rogers
Bendix Friction Materials Div.
P. O. Box 238
Troy, NY 12181

Dear Mr. Rogers:

The following is a temporary L1516 warning label to be used for Ford asbestos brake linings as verbally instructed by our Mr. W. R. Rooney, Office of the General Council, November 6, 1986:

"DANGER: CONTAINS ASBESTOS FIBERS. AVOID CREATING DUST. CANCER AND LUNG DISEASE HAZARD. WHEN SERVICING THIS BRAKE LINING OR ANY COMPONENT RELATED TO IT OR LOCATED NEAR IT, PREVENT ASBESTOS DUST FROM BECOMING AIRBORNE BY VACUUMING THE ASSEMBLY WITH AN INDUSTRIAL TYPE VACUUM CLEANER EQUIPPED WITH A HIGH EFFICIENCY FILTER SYSTEM AND BY WASHING THE ASSEMBLY WITH AN APPROPRIATE BRAKE PARTS WASHER IF NECESSARY. NEVER REMOVE DUST OR DIRT FROM THIS ASSEMBLY BY BLOWING WITH COMPRESSED AIR."

We appreciate Bendix bring this matter to our attention.

B. R. Wales

B. R. Wales

cc: Mr. G. W. Howard
Mr. R. J. Rabias
Mr. W. R. Rooney

*Note: 1-7-87
G. Thayer on 11-10-86
sent a letter to G. Teato for
implementation of this change with
our Vendor. A one time \$30 die change
was incurred this will not be passed
along to our customer
M. Gillman*