

ACME, TEXAS PLANT FORMULA

READY MIX JOINT COMPOUND TEX-976-Y (MACHINE TOOLS) (READY MIX "X")

DESCRIPTION OF PRODUCT - Yellow Ready Mix Joint compound used for taping, covering tape, filling cornerhead and spotting nails.

<u>FORMULA</u> <u>Raw Material</u>	<u>Function</u>	<u>R.M. Spec.</u>	<u>Percent</u>	<u>Lbs./Batch</u>
Water	Solvent	-	-	433.0 ; (52 gal.)*
Filler C-971	Body	-	91.32	700.0
Poly Vinyl acetate Emulsion	Adhesive	185	8.03	61.5
Benzoflex 50	Plasticizer	183	.52	4.0
Yellow Oxide 2087	Pigment	139	.13	1.0
			100.00	1199.5**

*Approximately 56.5 lbs/100 lbs of active ingredients (this may vary $\pm$ 2 gallons per batch).

**One batch yields 18 (+) - 5 gallon pails of Ready Mix Joint Compound at 65.6 lbs/pail.

WORKING CONSISTENCY - Refer to Plant Testing Procedure No. 32.

Specifications for Paste: If paste is not proper working consistency, a maximum of 5 cc water per 150 grams of paste may be added to adjust.

Brabender - 385 $\pm$ 20 / 5

WORKING PROPERTIES - Refer to Plant Testing Procedure No. 33.

Specifications: Compound shall be plastic, buttery working, and free of any coarse, gritty, or undispersed particles. Material shall be free from lumps due to incomplete mixing.

BONDING PROPERTIES - Refer to Plant Testing Procedure No. 35.

Specifications: After compound has dried, tape shall show at least 75% fiber tear when delaminated.

CRACK RESISTANCE - Refer to Plant Testing Procedure No. 37.

Specifications: There shall be no large fissure cracks in the wedge, and no cracks in the thinner half of the wedge.

COLOR - Yellow

Specifications: Dried compound shall match color of standard sample.

ACME, TEXAS PLANT FORMULA

READY MIX JOINT COMPOUND TEX-976-Y (MACHINE TOOLS) (READY MIX "X")

DESCRIPTION OF PRODUCT - Yellow Ready Mix Joint compound used for taping, covering tape, filling cornerbead and spotting nails.

-/

<u>FORMULA</u> <u>Raw Material</u>	<u>Function</u>	<u>R.M. Spec.</u>	<u>Percent</u>	<u>Lbs./Batch</u>
Water	Solvent	-	-	433.0 ; (52 gal.)*
Filler TEX-970	Body	-	91.32	700.0
Elvacet 81-900	Adhesive	185	8.03	61.5
Benzoflex 50	Plasticizer	183	.52	4.0
Yellow Oxide 2087	Pigment	139	.13	1.0
			100.00	1199.5**

*Approximately 56.5 lbs/100 lbs of active ingredients (this may vary $\pm$ 2 gallons per batch).

**One batch yields 18 (+) - 5 gallon pails of Ready Mix Joint Compound at 65.6 lbs/pail.

WORKING CONSISTENCY - Refer to Plant Testing Procedure No. 32.

Specifications for Paste: If paste is not proper working consistency, a maximum of 5 cc water per 150 grams of paste may be added to adjust.

Brabender - 385 $\pm$ 20

WORKING PROPERTIES - Refer to Plant Testing Procedure No. 33.

Specifications: Compound shall be plastic, buttery working, and free of any coarse, gritty, or undispersed particles. Material shall be free from lumps due to incomplete mixing.

BONDING PROPERTIES - Refer to Plant Testing Procedure No. 35.

Specifications: After compound has dried, tape shall show at least 75% fiber tear when delaminated.

CRACK RESISTANCE - Refer to Plant Testing Procedure No. 37.

Specifications: There shall be no large fissure cracks in the wedge, and no cracks in the thinner half of the wedge.

COLOR - Yellow

Specifications: Dried compound shall match color of standard sample.

September 16, 1968
NEW FORMULA

ACME, TEXAS PLANT FORMULA

READY MIX JOINT COMPOUND TEX-976-Y (MACHINE TOOLS) (READY MIX "X")

DESCRIPTION OF PRODUCT - Yellow Ready Mix Joint compound used for taping, covering tape, filling cornerbead and spotting nails.

<u>FORMULA</u>				
<u>Raw Material</u>	<u>Function</u>	<u>R.M. Spec.</u>	<u>Percent</u>	<u>Lbs./Batch</u>
Water	Solvent	-	-	433.0 ; (52 gal.)
Filler C-971	Body	-	91.32	700.0
Poly Vinyl Acetate Emulsion	Adhesive	185	8.03	61.5
Benzoflex 50	Plasticizer	183	.52	4.0
Yellow Oxide 2087	Pigment	139	.13	1.0
			100.00	1199.5**

*Approximately 56.5 lbs/100 lbs of active ingredients (this may vary $\pm$ 2 gallons per batch).

**One batch yields 18 (+) - 5 gallon pails of Ready Mix Joint Compound at 65.6 lbs/pail.

WORKING CONSISTENCY - Refer to Plant Testing Procedure No. 32.

Specifications for Paste: If paste is not proper working consistency, a maximum of 5 cc water per 150 grams of paste may be added to adjust.

Brabender - 385 $\pm$ 15

WORKING PROPERTIES - Refer to Plant Testing Procedure No. 33.

Specifications: Compound shall be plastic, buttery working, and free of any coarse, gritty, or undispersed particles. Material shall be free from lumps due to incomplete mixing.

BONDING PROPERTIES - Refer to Plant Testing Procedure No. 35.

Specifications: After compound has dried, tape shall show at least 75% fiber tear when delaminated.

CRACK RESISTANCE - Refer to Plant Testing Procedure No. 37.

Specifications: There shall be no large fissure cracks in the wedge, and no cracks in the thinner half of the wedge.

COLOR - Yellow

Specifications: Dried compound shall match color of standard sample.

November 4, 1968
Supersedes Formula No. TEX-976-Y
Dated September 16, 1968

ACME, TEXAS PLANT FORMULA

READY MIX JOINT COMPOUND TEX-976-Y (MACHINE TOOLS) (READY MIX "X")

DESCRIPTION OF PRODUCT - Yellow Ready Mix Joint compound used for taping, covering tape, filling cornerbead and spotting nails.

-/

<u>FORMULA</u>	<u>Function</u>	<u>R.M. Spec.</u>	<u>Percent</u>	<u>Lbs./Batch</u>
<u>Raw Material</u>				
Water	Solvent	-	-	433.0 (52 gal.)*
Filler TEX-970	Body	-	91.32	700.0
Elvacet 81-900	Adhesive	185	8.03	61.5
Benzoflex 50	Plasticizer	183	.52	4.0
Yellow Oxide 2087	Pigment	139	.13	1.0
			100.00	1199.5**

*Approximately 56.5 lbs/100 lbs of active ingredients (this may vary $\pm$ 2 gallons per batch).

**One batch yields 18 ($\pm$) - 5 gallon pails of Ready Mix Joint Compound at 65.6 lbs/pail.

WORKING CONSISTENCY - Refer to Plant Testing Procedure No. 32.

Specifications for Paste: If paste is not proper working consistency, a maximum of 5 cc water per 150 grams of paste may be added to adjust.

Brabender - 385 $\pm$ 20

WORKING PROPERTIES - Refer to Plant Testing Procedure No. 33.

Specifications: Compound shall be plastic, buttery working, and free of any coarse, gritty, or undispersed particles. Material shall be free from lumps due to incomplete mixing.

BONDING PROPERTIES - Refer to Plant Testing Procedure No. 35.

Specifications: After compound has dried, tape shall show at least 75% fiber tear when delaminated.

CRACK RESISTANCE - Refer to Plant Testing Procedure No. 37.

Specifications: There shall be no large fissure cracks in the wedge, and no cracks in the thinner half of the wedge.

COLOR - Yellow

Specifications: Dried compound shall match color of standard sample.

**ACME FORMULA #976Y
ASBESTOS CONTAINING PRODUCTS**