

**C-8 PERSONAL AIR MONITORING DATA
WASHINGTON WORKS - SPD COPOLYMERS AREA (1988)**

(AEL IS 0.56 PPB)

JOB NAME/PERS CODE	NO. OF SAMPLES	GEOM. MEAN (PPB)	MAX. (PPB)	812T ACCEPTANCE	95TH XTILE (PPB)
FEP FOREMAN/PROJECTS /SAFETY - 18AA	4	0.05	0.10	NEED MORE DATA	0.16
FEP POLYKETTLE OPERATOR - 18PA	8	<0.03	0.39	NEED MORE DATA	0.76
FEP EXTRUSION/OVEN OPERATOR - 18PP	6	<0.03	0.03	YES	<0.03
FEP NET FINISHING OPERATOR - 18PC	8	0.08	0.12	YES	0.15
FEP CUBE/PACKOUT OPERATOR - 18PD	6	<0.03	0.04	YES	<0.03
COPOLYMERS GENERAL SHIFT MECHANIC - 68MA	7	<0.03	0.06	YES	<0.06
FEP E&I MECHANIC - 68MB	7	<0.03	<0.03	YES	<0.03
FEP GENERAL DAY MECHANIC - 68ME	9	0.06	0.31	YES	0.73

J.B. Loschiavo
February 27, 1989

RJZ00912

EID951513

**C-8 PERSONAL AIR MONITORING DATA
WASHINGTON WORKS - SPD POLYMERS AREA (1988)**

(AEL IS 0.56 PPB)

<u>JOB NAME/PERS CODE</u>	<u>NO. OF SAMPLES</u>	<u>GEOM. MEAN (PPB)</u>	<u>MAX. (PPB)</u>	<u>812T ACCEPTANCE</u>	<u>95TH XTILE (PPB)</u>
POLY FINE POWDER/ DISP. FOREMAN - 08AA	8	~0.03	0.10	NEED MORE DATA	0.12
POLY AUTOCLAVE OPERATOR - 08PE	7	0.09	0.30	NEED MORE DATA	0.56
POLY POLYKETTLE OPERATOR - 08PF	7	0.05	0.15	NEED MORE DATA	0.13
POLY DISPERSION OPERATOR - 08PH	15	0.03	0.09	YES	0.08
POLY DRYER/ENVIR. CONTROL OP. - 08PI	15	<0.03	0.34	YES	0.25
POLY FINE POWDER PACKOUT OP. - 08PJ	7	<0.03	0.18	NEED MORE DATA	---
POLY MAINTENANCE FOREMAN - 58AB	6	<0.03	0.11	NEED MORE DATA	---
POLY GENERAL DAY MECHANIC - 58MC	8	<0.03	0.12	NEED MORE DATA	~0.06
POLY GENERAL SHIFT MECHANIC - 58MD	4	<0.03	<0.03	NEED MORE DATA	~0.03
POLY E&I PROJECTS/ COD MECHANIC - 58ME	6	<0.03	0.05	YES	~0.03
POLY PROCESS E&I MECHANIC - 58MG	8	<0.03	0.08	YES	~0.08

J.G. Loschiavo
February 27, 1989

RIZ009913

EID951514