

JUNE '79 - Nov '79

DTH 000079715

47
43
90

DTH 000079716

"A" CONT.

11. Loaded 41596 - 5385 - from 675-6-7-8, after took silo outlager, will show on 6-17 report.

12. Bagged 36 Shls, this shift, 5305.

71704 13. Need one more blend 5305, after the one we're on @ 0700, then go 5385 to high shls.

14. 0700 1900 "C" Reamed

① Larry says sac.

② Had shift maint replace the belts in the chisperm on #7 pulse air

③ Shift maint check the oil in D300 Rv gear box for water it was ok.

④ #2 Activator top loading valve stuck in open position called in Elb maint checked

⑤ out found the top valve was damaged some called in maint help change out.

⑥ The bird chute vibrator fell off of #5 bird chute Shift maint replaced.

⑦ #5 flamed out could not get it to start. Called for Mex. help. could not get in touch with Mex. Had the guard to call. Elb maint. Top Adams came in on same.

⑧ Finished bagging the 5305 blend & started 5385 direct from #1 dryer.

⑨ Emptied 575 silo of 5305 to use for bagging 5385 from in order to keep dryer rates high

DTH 000079718

⑩ Finished 882 - 686

576 578 450 491 - 282