


JACKSONVILLE, FLORIDA
STANDARD OIL COMPANY
OF KENTUCKY



Reorder No. 912 $\frac{1}{8}$

PARK BRAND FOLDER
MEDIUM HEAVY WEIGHT

KE 0021126

N 24498

spent inside the tank, etc.

An Ethyl Corporation representative attended the operation every evidence that he was very careful in his observation of known that not infrequently men remove their masks when inside this may have occurred. There is no evidence that either of the symptoms were closely questioned about this.

Including the foreman there were 12 men involved in this of the 12 worked inside the tank.

Two men had symptoms of insomnia but the one man (Dowley) tank until after cleaning was completed and symptoms were so not examined by the Ethyl Corporation physician.

The second man's symptoms were confined to insomnia, nervous and headache and the Ethyl Corporation physician had reason to intoxication. However, in view of the urine lead concentration per liter, presuming that the urine was not contaminated, a diagnosis the records should be made of tetraethyllead intoxication. It the man's condition may have worsened after he was seen.

- 12 men involved on job
- 7 worked within the tank
- 1 suspected tetraethyllead illness
- 1 confirmed tetraethyllead intoxication

Factors responsible:

Not known but man may have removed mask at times with was not observed. Man was completely inexperienced.

11- 1-1963

Lester W. Sanders

- RE 0021127