

Pittsburgh Corning Corporation
P.O. Box 3 57
Tyler, Texas 757 1

JANUARY 17, 1972

ASST. REGIONAL ADMINISTRATOR - COMPLIANCE
U. S. DEPARTMENT OF LABOR
OCCUPATIONAL SAFETY & HEALTH ADMINISTRATION
SUITE 600, TEXACO BUILDING
1512 COMMERCE STREET
DALLAS, TEXAS 75201

PROGRESS REPORT - CITATION OF ALLEGED OSHA VIOLATIONS

ITEM 1 - 29 CFR, 1910 134 (b) (10)

NEW PERSONNEL WILL BE GIVEN A PHYSICAL WITHIN 30 DAYS OF HIRING.

NOTE: DUE TO THE RAPID TURNOVER OF NEW EMPLOYEES, THE COMPANY IS NOT GIVING PRE-EMPLOYMENT PHYSICALS UNTIL AN EMPLOYEE HAS BEEN EMPLOYED FROM TWO TO FOUR WEEKS.

ITEM 2 - 29 CFR, 1910 134 (A) (1)

THREE OPEN AIR DISCHARGE VENTS ON AIR CYLINDERS OF LARGE SAW HAVE BEEN PIPED INTO CEILING AREA. CORRECTED ON DAY AFTER INSPECTION, DECEMBER 10, 1971. A FOURTH AIR DISCHARGE VENT FROM AN AIR CYLINDER ON THE LARGE SAW HAS BEEN PIPED INTO THE ATTIC AREA, CORRECTED DECEMBER 10, 1971.

ALL OPEN DOORS ON EAST SIDE OF PLANT BUILDING ARE KEPT CLOSED AND SIGNS ARE ON ORDER TO BE POSTED IN THE AREAS AS SOON AS RECEIVED, CORRECTED DECEMBER 10, 1971.

USE OF COMPRESSED AIR TO BLOW OFF CUT INSULATION PIPE SECTIONS AT END OF CONVEYOR HAS BEEN DISCONTINUED AND THE PIPING HAS BEEN DISCONNECTED. CORRECTED DECEMBER 10, 1971.

COMPRESSED AIR IS NO LONGER BEING USED TO BLOW OFF EQUIPMENT. SUCTION TUBES HAVE BEEN INSTALLED OVERHEAD AND FLEXIBLE HOSES NOW "VACUUM" THE EQUIPMENT. INSTALLED JANUARY 9, 1972.

BB 0019168

SOLID BACK UP BLOCK FOR BLOCK SAW HAS BEEN REDESIGNED AND WILL BE INSTALLED AS SOON AS IT IS COMPLETED. UNTIL THE NEW BACK UP BLOCK IS RECEIVED FROM THE SHOP, THE EQUIPMENT WILL NOT BE USED.

THIS DOCUMENT WAS NOT A RECORD OF
PPG INDUSTRIES, INC. DID NOT COME FROM
IT'S FILES AND CANNOT BE AUTHENTICATED
BY PPG INDUSTRIES, INC.

1698

P I T T S B U R G H P P G C O R N I N G

ITEM 2 - 29 CFR 1910 134 (A) (1) - CONT.

ALL FEEDERS IN USE HAVE BEEN SEALED ON THE BACK SIDE. DATE COMPLETED JANUARY 15, 1972. OPEN INSPECTION PLATES ARE BEING KEPT CLOSED AND FEEDER OPERATORS HAVE BEEN SO INSTRUCTED. ALL MISCELLANEOUS OPENINGS ON SIDES ARE BEING SEALED. THIS WILL BE COMPLETED JANUARY 29, 1972.

A REGULAR SET SCHEDULE HAS BEEN DESIGNATED AND WILL BE FOLLOWED FOR INSPECTION OF VENTILATION SYSTEM TO PREVENT PLUGGING. JANUARY 13, 1972.

ITEM 3 - 29 CFR 1910 141 (A) (3) (11)


HOUSEKEEPING PRACTICES HAVE BEEN CHANGED.

- A. WORK AREAS ARE CLEARED IMMEDIATELY AFTER USE.
- B. FIBER AND DUST IS NOW "VACUUMED" UP INTO THE MAIN DUST COLLECTOR.
- C. THREE SUCTION DOWNSPOUTS HAVE BEEN INSTALLED IN THE FINISHING DEPARTMENT FOR USE WITH FLEXIBLE HOSES. JANUARY 9, 1972.

OTHER DOWNSPOUTS ARE SCHEDULED FOR THE BATCH AND PRODUCTION AREAS AS SOON AS THEY CAN BE INSTALLED - THUS NO COMPRESSED AIR WILL BE USED (IN-PLANT) TO CLEAN OFF MACHINERY AND EQUIPMENT. PROPOSED DATE OF COMPLETION JANUARY 23, 1972.

THE SUBJECT OF PROPERLY WORN RESPIRATORS IN THE PLANT HAS BEEN DISCUSSED WITH THE CHAIRMAN OF THE WORKMENS' COMMITTEE. THE UNION (OCAW) HAS ALSO BEEN ADVISED THAT EACH EMPLOYEE HAS A RESPONSIBILITY TO CONFORM TO AND OBEY PLANT SAFETY RULES AND REQUIREMENTS UNDER OSHA AND THAT FAILURE TO DO SO COULD RESULT IN DISCIPLINARY ACTION INCLUDING THE PENALTY OF SUSPENSION OR DISCHARGE. JANUARY 10, 1972.

PITTSBURGH CORNING CORPORATION



C. E. VAN HORNE
WORKS MANAGER
PLANT 7, TYLER, TEXAS

CEVH/EM

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

1 BB 0019169 1

THIS DOCUMENT WAS NOT A RECORD OF
PPG INDUSTRIES, INC. DID NOT COME FROM
IT'S FILES AND CANNOT BE AUTHENTICATED
BY PPG INDUSTRIES, INC.

1699