

T. J. Lang

Personnel Manager Chemical

Nov. 11, 19
Trenton Chemica

D. L. Eschelbach

Industrial Hygiene Personnel

Highland Park

Union Industrial Hygiene Investigation

EXHIBIT

CHR-78

The disc brake operations located in the Friction Materials Building were observed by Mr. D. A. Padden, International U.A.W. industrial hygienist, on November 7, 1969. At the conclusion of the work environment investigation the following items were reviewed during a meeting of management and union representatives.

1. Dust Collector. Asbestos dust falls from the clean-out door, located above the work area, when the screw conveyor becomes plugged and cleaning is required. Information obtained from a representative of the Engineering Department indicates that improvement of existing equipment is planned. We were informed that a decrease in the speed of material transferring from the collector to the conveyor is contemplated in an effort to balance the system.
2. Hammer Mill Balcony. Cleanup of floor with a squeegee rather than a broom, as performed during the plant visit was considered to be satisfactory.

~~CONFIDENTIAL - SECURITY INFORMATION~~

D. L. Eschelbach, Chief
Industrial Hygiene Department

bm

cc: A. Atkinson
W. F. Davinger
R. F. Bowers
P. E. Repucci
N. A. Trombley