

PLAINTIFF'S
EXHIBIT
WB-910



Westinghouse

Date 4/17/63

From Lester Works - G Bldg.

Subject STEAM SUPERVISOR'S LETTER
NO. 63-12

Index INSULATION, SPRAYED-ON,
JACKETS

Route N.L. #3-8

Recently a customer reported a substance had leaked out of the insulation Westinghouse had sprayed on the inside of the metal jacket on one of their outdoor units.

This white substance had run down over some electrical connections and corroded the terminals. The painted surface was also marred by streaks.

We are asking our District Offices to report any cases, past or near future, in which the sprayed-on insulation of the metal jackets has exhibited a similar property.

T. W. Bonham

Div. Steam Service Dept. - T. W. Bonham
nl

28045534