

ABEX LINING REVIEW

SUMMARY OF PROBLEM

1. 1980 VALIDATION WITH DM 5470
2. 1980 VALIDATION WITH DM 8011
3. 1980 PRODUCTION COMPLAINTS
4. 1981 DEVELOPMENT WITH DM 8032A

GLBUYCK  
10-11-79/MS