

introduction of "flow-line" servicing at Dealers works, in which one individual may be engaged almost entirely on brake servicing, emphasises this point.

Our environmental studies have not included maintenance procedures which involve the filing or grinding of brake lining material, and we would envisage that these would give rise to considerably increased air contamination by chrysotile asbestos, with the attendant need for strict precautions to prevent the inhalation of fibres.

REFERENCES

- COMMITTEE ON HYGIENE STANDARDS, BRITISH OCCUPATIONAL HYGIENE SOCIETY (1968) *Hygiene Standards for Chrysotile Asbestos Dust*, Pergamon Press, Oxford.
- HOLMES, S. (1967) Private communication.
- LYNCH, J. R. (1968) *J. Air Pollut. Control Ass.* 18, 824.