

FILE NAME: Westinghouse (WH)

DATE: 1970 Mar 6

DOC#: WH021

DOCUMENT DESCRIPTION: Memo RE Caution Stating "Don't Breathe Dust"

Machining Micarta  
etc. as per tag.  
(ash)

1970

---

March 6, 1970

J. Welton

Machining of ~~asbestos~~ produces asbestos dust.  
Do not breathe dust. Provide adequate ventilation.  
See SPDC A-20.

Following is a partial list of the cards that should include this caution. I suspect that I missed some when I reviewed the cards.

[illegible]Zella E. Boos  
Headquarters Industrial Hygiene

03117713