

10 Mickey Blackwell

From Alton Reener

Date 5/6/82

Subject D300 leakage lid gasket.

Polky
Hawkins
copy

On the 5/6/82 at 1300 we started picking up his van reading from the top of D400 & D600. Of his children went up to check out the area. to find the leakage lid O-ring gasket leaking ^{at D300} - he then informed Alton Reener of the problem & went to the top of D10 VII LX north of D300 to check on the leak. I could hear the vapor from the north side of the reactor flowing out. The leak was on the front side facing the south. at this time I gave the word to him and reconvered the batch. We then checked the area on the ground level for vapor with the HAV unit but did not detect any reading. the only reading that we picked up on the homopolymer was from the top of D400 & D600 LX the wind was from the north blowing to the south of the area. all personnel were informed to stay out of the area ~~until~~ or if needed they would have to wear breathing protection until the batch could be reconvered. The batch was reconvered and the O-ring gasket changed out. The gasket was broken apart when ~~the batch was reconvered~~ we opened the LX

Alton Reener

DTH 000105240