

5. All table and floor cleaning in areas where brakes and clutches are repaired shall be done with the HEPA vacuum cleaner as described in (2) above. Grinding and riveting machines shall also be cleaned with such a cleaner and the remaining dust wiped with a water dampened cloth. A NIOSH certified respirator approved for asbestos shall be used during this cleaning.
6. If not in effect, a respirator program shall be established in accordance with the Occupational Safety and Health Administration (OSHA) Standard, Title 29, U.S. Code of Federal Regulations (CFR), Part 1910.134.
7. HEPA vacuum cleaner filters containing asbestos dust, cloths or brushes used for wiping brake and clutch assemblies, and all liquid used for wet brushing shall be disposed of in accordance with U.S. Environmental Protection Agency (EPA) regulations. These regulations state that the asbestos waste shall be disposed of in sealed impermeable bags or other containers at a disposal site which meets EPA criteria for asbestos disposal. Also, the waste containers shall display the following warning label or tag printed in letters of sufficient size and contrast to be visible and legible:

CAUTION
Contains Asbestos Fibers
Avoid Breathing Dust
Breathing Asbestos Dust May Cause Serious Bodily Harm

The EPA regulations for proper asbestos waste disposal are detailed in Title 40, CFR, Part 61, Subparts A and B.