

ST. LOUIS - GENERAL OFFICES

DECEMBER 2, 1968

UNITED RESINS/AROCLOR 5460

G. W. MILLER - ANNISTON

H. L. WILLIAMS - ANNISTON

R. A. HAYDEL - ANNISTON

J. E. SCHNEPP/W. A. KUEHN

V. R. HAUPT - ANNISTON

As you know, United Resins have often complained of black specks in their Aroclor 5460. On August 13, Gerry Miller wrote me to say that you were arranging for installation of a spool piece in the new packing system to allow future installation of an appropriate filter. Has this been accomplished now, and if so, can we tell United Resins we have taken action to correct the problem? If we have, this would be a help in customer relations.

C. PATON

RS

V. R. Haupt
Anniston

Expect new flake to
solve prob. (about 12/15/68)
we'll install filter on
feed stream. This is not an
easy filtration - will require
a thermal jacketed installation
which may take several months
to design & install (if required)

Pls return of
8100 follow