

Memorandum

Bendix

Bendix Friction Materials Division
Green Island, New York

✓ TO: G. Teatr

J. Eubanks

cc: C. Little

C. Thorne

W. H. H. H.

Allied Signal

Date: May 26, 1987

To: A. Schuttenhelm, S.W. Scott

From: E.L. Rogers

Subject: FORD OES CARTON LABELS

Attached will be
Standard for "Asbestos
Warning Label" for
Ford Parts & Service.

~~Change with~~
notify your suppliers
regarding change

After several months of internal negotiations, Ford has finally released a new version of their L-1516 brake lining packaging specification. It is now combined with their clutch parts label and is renumbered to "L-1517" (see attached spec dated 5/18/87). This version replaces the verbal instructions issued in November 1986.

Action - Please advise your carton suppliers to print this new L-1517 version on all Ford OES cartons which require the old L-1516 asbestos warning label as soon as they can obtain the required photo polymer plate.

We recognize that certain cartons (eg D5HZ-2007-K, L, M, N and E6DZ-2007-A, B, etc.) do not require such a label and caution you that your directions to these suppliers should not require the use of the new L-1517 imprint on "ALL" Ford cartons.

At a later date, Ford Parts and Service Division will issue revised packaging specifications for each part number which will show the new L-1517 requirement.

E L Rogers

E.L. Rogers

ELR:yj

Attachment

cc: C.M. Brunhofer
R.J. Hart
G.W. Howard
R.H. Michaud

Bill Halpin
Keep on file, please
Rev 5/28/87

ID-R214

HWBUI0012428