

MAR-79

National
Headquarters

SEARS, ROEBUCK AND CO.
SEARS TOWER
CHICAGO, ILLINOIS 60684

May 22, 1980 *RS/28*

Mr. L. L. Sealy
MAREMONT CORPORATION
200 East Randolph Drive
Chicago, IL 60601

Dear Dick:

Per our discussion, attached is a response from
Sears lab regarding warning labels for asbestos
dust on Sears brake packaging. Since Sears no
longer grinds brake shoes in our auto centers,
nor do we expect our customers to grind shoes,
our lab feels we do not need a warning label
on our packaging.

Do you and Nuturn concur? Please advise.

Very truly yours,

SEARS, ROEBUCK AND CO.

T. B. Flannery
T. B. Flannery
Assistant Buyer
Department 628

TBF/dlm

Att:

EXHIBIT	
NO.	<i>P-27</i>
DATE	<i>1-13-84</i>
EVD.	☐ IDENT ☒

Over to

71 67