

PERSONNEL MONITORING CARD

PLANT BUILDING NO.		SOCIAL SECURITY NO.												LAST NAME		INITIALS		DATE		FLASHER TUBE NUMBER																					
1	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	H	O	G	A	N	R		MO.	DAY	YEAR	5	0	9	3												
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

JOB CODE	SPECIFIC TASK NO.	RESULT (PPM)	TIME START	EXPOSED TIME	FLASHER TUBE NUMBER																																		
033	000	0.2	1230	380	A																																		
41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

PUMP NUMBER	11
EMPLOYEE SIGNATURE	
THIS IS TO SHOW THAT I HAVE SEEN THE RESULT OF MY SAMPLE. DATE 7-30-71	
SIGNATURE <i>R. M. [Signature]</i>	

SPL. VOLUME	TOTAL VCM

SHIFT	A	B	C	D	E	F	G	H
DEPT.	5162	SUPERVISOR <i>[Signature]</i>						

REMARKS: