

DATE: 2/14/92

MASTER NO. 431809 A

Section V — Reactivity Data

Stability	Unstable		Conditions to Avoid
	Stable	X	

Impairability (Materials to Avoid) None

Hazardous Decomposition or Byproducts None

Hazardous Polymerization	May Occur		Conditions to Avoid
	Will Not Occur	X	

Section VI — Health Hazard Data

Route(s) of Entry:	Inhalation?	Yes	Skin?	No	Ingestion?	No
--------------------	-------------	-----	-------	----	------------	----

Health Hazards (Acute and Chronic)

Acute: no immediate reaction to overexposure.

Chronic: long term overexposure may cause asbestosis, lung cancer and mesothelioma of the pleura and peritoneum.

Carcinogenicity:	NTP?	Yes	IARC Monographs?	Yes	OSHA Regulated?	Yes
------------------	------	-----	------------------	-----	-----------------	-----

Signs and Symptoms of Exposure None

Medical Conditions
Generally Aggravated by Exposure Symptoms of variable cough, dispnea, chest pains, weakness and decreased chest expansion.

Emergency and First Aid Procedures
No acute toxicity. Avoid breathing dust. Remove from exposure and see an occupational physician.

Section VII — Precautions for Safe Handling and Use

Steps to Be Taken in Case Material Is Released or Spilled

Use approved respiratory and protective equipment. Clean with HEPA filtered vacuuming equipment and/or, if sweeping is necessary, wet down the spillage. Place all material in sealed impermeable bags or other closed impermeable containers.

Waste Disposal Method

Dispose of material in accordance with all federal, state or local air pollution and solid waste regulations. Recommend disposal in an EPA approved hazardous waste land fill.

Precautions to Be Taken in Handling and Storing

Local exhaust ventilation, material wetting and/or respiratory protection is required for all sawing, grinding, cutting, bulk handling, spraying, demolition, removal or other activities where dust exposure may occur.

Other Precautions

Smoking greatly increases the risk of serious bodily harm.

Section VIII — Control Measures

Respiratory Protection (Specify Type) Air purifying respirator with H.E.P.A filters (except disposable respirator) or supplied-air respirator (see OSHA standards 1910.1001 g and 1928.56h)

Ventilation	Local Exhaust	Required	Special
	Mechanical (General)		Other

Protective Gloves Required Eye Protection Recommended
Dust may cause irritations and abrasions

Other Protective Clothing or Equipment Protective clothing is required if exposure exceeds the OSHA permissible exposure limit or significant contact occurs.

Work/Hygiene Practices

Avoid creating dust. Use all dust control equipments. Use personal protective equipment. Remove all work clothing before leaving plant. Practice good house keeping and good personal hygiene procedures. Do not smoke.