

051010375

CAUTION

ASBESTOS DUST HAZARD

- DO NOT BREATHE DUST
- DO NOT HOSE OFF WITH COMPRESSED AIR
- DO NOT MACHINE UNLESS DUST COLLECTION EQUIPMENT IS CONTROLLING DUST

Respirators must be worn to avoid exposure to dust.
Dispose of dust in a sealed container marked with appropriate warning for Asbestos.

THE S.K. WELLMAN CORP.
ENGINEERED FRICTION MATERIALS

A-713

CAUTION

ASBESTOS DUST HAZARD

- DO NOT BREATHE DUST
- DO NOT HOSE OFF WITH COMPRESSED AIR
- DO NOT MACHINE UNLESS DUST COLLECTION EQUIPMENT IS CONTROLLING DUST

Respirators must be worn to avoid exposure to dust.
Dispose of dust in a sealed container marked with appropriate warning for Asbestos.

THE S.K. WELLMAN CORP.
ENGINEERED FRICTION MATERIALS

A-713