

OCCUPATIONAL SAFETY AND HEALTH ADMINISTRATION

CITATION and NOTIFICATION OF PENALTY

Belle Mead Area Office
GSA Belle Mead Depot, Bldg. T-3
Belle Mead, NJ 08502

ISSUANCE DATE	OSHA NUMBER	
5/6/82	17558	153
REGION	AREA	PAGE
02	2140	1 OF 1

TYPE OF VIOLATION(S)	CITATION NO.
OTHER	1

CERTIFIED MAIL-RRR

TO:

Union Carbide Corporation
P.O. Box 670
Bound Brook, New Jersey 08805
Attn: Mr. Eric Baumann
Personnel Safety Coordinator

INSPECTION DATE:

4/1-5/3/82

INSPECTION SITE:

1 River Road
Piscataway, NJ 08805

THE LAW REQUIRES that a copy of this Citation be posted immediately in a prominent place at or near the location of the violation(s) cited below. The Citation must remain posted until the violations cited below have been corrected, or for 3 working days (excluding weekends and Federal holidays) whichever is longer.

PENALTIES
ARE DUE
WITHIN 15
DAYS OF
RECEIPT
OF THIS
NOTIFICATION
UNLESS
CONTESTED
(See enclosed
Booklet)

This Section Must
Be Detached
Before Posting

This citation describes violations of the Occupational Safety and Health Act of 1970. The penalty(ies) listed below are based on these violations. You must correct the violations referred to in this citation by the dates listed below and pay the penalties proposed, unless within 15 working days (excluding weekends and Federal holidays) from your receipt of this citation and penalty you mail a notice of contest to the U.S. Department of Labor Area Office at the address shown above. (See the enclosed booklet which outlines your responsibilities and courses of action and should be read in conjunction with this form.)

ITEM NUMBER STANDARD, REGULATION OR SECTION OF THE ACT VIOLATED: DESCRIPTION	DATE BY WHICH VIOLATION MUST BE CORRECTED	PENALTY
The issuance of this citation does not constitute a finding that a violation of the Act has occurred unless there is a failure to contest as provided for in the Act or, if contested, unless the citation is affirmed by the Review Commission. The violations described in this citation are alleged to have occurred on or about the day the inspection was made unless otherwise indicated within the description given below. 1 29 CFR 1910.1001(f)(1): Initial monitoring was not conducted in such a manner to determine whether every employee's exposure to airborne asbestos fibers is below the prescribed limits: a) Tunnel which contains utility lines and process lines. Two maintenance mechanics removing asbestos insulation from pipes. 2 29 CFR 1910.1001(g)(1)(i): Asbestos caution signs were not posted in such a manner so employees could read them and take necessary protective steps before entering an area marked by the signs: a) Tunnel which contains utility lines and process lines. Employees removing asbestos insulation from pipes.	5/3/82 5/3/82	\$0 \$0

PLAINTIFF'S EXHIBIT

UC-2936

UCC 016231