

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	2/24/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Daylight Petroleum, LLC	
Facility Name:	Strawn Unit	
Facility Physical Location:	33.8520564, -97.2236884	
(city, state, zip code)	Sivells Bend, Texas 76240	
Mailing address:	1999 Bryan St., Ste. 900	
(city, state, zip code)	Dallas, Texas 75201	
County/Parish:	Cooke County	
Facility Phone Number	(312) 475-0869	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU0011037	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Jeanne Eckhart	EPA 6 ECDWE	Inspector
Kayla Woods	EPA 6 ECDWE	Inspector
EPA Lead Inspector Signature/Date		
	Jeanne Eckhart	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Jeanne Eckhart and Kayla Woods visited the Daylight Petroleum, LLC oil and gas facility located near Sivells Bend, Texas on 02/24/2020 for an unannounced inspection. There were no representatives of Daylight Petroleum, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This previous discharge was located on the Strawn Unit from a flow line associated with oil and gas production. The EPA inspectors conducted a creek survey, downstream of a previous point of discharge spot from a flow line. This was a previous site of EPA enforcement action (EPA ID: TX0011037, and EPA Administrative Order Docket No.: CWA-06-2015-1755). The site of the previous spill from this location was indicated to be from an underground flow line that ruptured.

Section II - OBSERVATIONS

During the creek survey, I observed a tributary of the Red River from the Farm to Market Road 1201. With a calibrated YSI Pro 30 conductivity meter, I measured 3,027 milligrams per liter (mg/L) Total Dissolved Solids (TDS) at that location in the tributary, which was downstream from the Strawn Unit.

Section III – AREAS OF CONCERN

There were elevated levels of TDS in the tributary of the Red River.

Section IV – FOLLOW UP

EPA water enforcement will conduct a follow up inspection as determined appropriate.

Section V – LIST OF APPENDICES

N/A