

BF Goodrich**INTER-ORGANIZATION CORRESPONDENCE**

TO	RONALD J. DAVIS	FIELD POINT OR DEPT. & BLDG. NO.	DATE YOUR LETTER
FROM	LOUIS CONERLY	PLAQUEMINE	DATE THIS LETTER
SUBJECT		PLAQUEMINE	04/15/91

NEAR MISS

SUMMARY AND CAUSE

ON MARCH 17, 1991 AT 2230 HOURS, WAS PUTTING VINYL FILTER 1F-7A BACK ON LINE WHEN HE TURNED AND SAW FIRE FLASHING OUT OF VINYL PUMP 1P-4A'S JUNCTION BOX. HE QUICKLY WENT AND SHUT THE PUMP DOWN AND BLOCKED IT IN AND TAGGED IT OUT. THERE ALSO WAS A VINYL LEAK ON A LINE FROM 1F-7A GOING TO THE RELIEF VALVE. PATCHED THE LEAK AND A WORK ORDER WAS WRITTEN TO REPAIR THE LEAK AND FOR I&E TO INSPECT THE JUNCTION BOX ON VINYL PUMP 1P-4A.

BOARD OF INQUIRY

A BOARD OF INQUIRY WAS HELD ON MARCH 21, 1991 WITH THE FOLLOWING IN ATTENDANCE:

T.J. GUILLOT	-	RESIN PRODUCTION COORDINATOR
JEFF CONKLIN	-	SAFETY ENGINEER
HEMAN CATIOR	-	MAINTENANCE COORDINATOR
DALE MARKS	-	MAINT. & I&E SUPERINTENDENT
JOHN SAXON	-	I&E FOREMAN
HAROLD STRICKLAND	-	CONTRACT ENGINEER
	-	OPERATOR SPECIALIST
LOUIS CONERLY	-	SHIFT FOREMAN

CORRECTIVE ACTION

1. I&E IS TO INSPECT ALL ELECTRIC PUMPS IN VINYL DAY TANK AREA FOR LOOSE CONNECTIONS.
2. I&E WILL P.M. ALL ELECTRIC EQUIPMENT ON A YEARLY BASIS.

REDACTED

NGC 13717

NARRATIVE

ON MARCH 17, 1991 . A VACATION RELIEF OPERATOR SPECIALIST WAS CLEANING A VINYL FILTER AND PUTTING IT BACK IN SERVICE WHEN HE SAW FIRE FLASHING FROM THE JUNCTION BOX OF 1P-4A (VINYL PUMP). HE QUICKLY WENT OVER AND SHUT THE PUMP DOWN AND CALLED HIS SHIFT FOREMAN, LOUIS CONERLY, TO COME OUT AND REPORTED THE INCIDENT TO HIM. HAD BLOCKED THE PUMP IN AND TAGGED IT OUT OF SERVICE. LOUIS CONERLY THEN WROTE A WORK ORDER FOR THE I&E DEPARTMENT TO INSPECT AND REPAIR THE EQUIPMENT.

FACTS SURROUNDING THE INCIDENT

1. WAS PERFORMING HIS NORMAL JOB FUNCTION.
2. THE CAUSE OF THE FIRE WAS A LOOSE CONNECTION OF THE WIRE LEADS.
3. THERE WAS NO DAMAGE OR INJURY FROM THE FIRE IN THE JUNCTION BOX.

LOUIS CONERLY

BD/231

NGC 13718