

MONITOR LARRY BECKHAM SHIFT 8-4 B DATE 12/16/78

OVA CALIBRATION .90 BACKGROUND 5ppm OVA NO. 2

PERMIT TO ENTER BUILDING 121 WITH OVA. FOREMAN *Forcellini* TIME 8 ⁴⁵

PERMIT TO ENTER LPA AND TANK FARM WITH OVA. FOREMAN TIME

BLDG. 121

POINT	RESULTS OF INVESTIGATING CAUSE FOR ALARMS OVER 3 PPM
5, 6	#26 Poly, bleed off valve was left open when Poly was charged, 7100,000 ppm, 1425, closed valve and bosed valve, notified operator and forman
5	#39 Poly had some vinyl in it when operator started HRC unit, 1415, 150 ppm
	#26 Poly caused several yellow and red lights,
	NUMBER OF RAND PAGE CALLS TO INVESTIGATE A ALARM <u>NONE</u>

[illegible]

LARGE POLY AREA

TAG	DESCRIPTION
2086	TK-3N bleed off valve leaking through, 0855, 150ppm bleed off valve is ABOVE MANHEAD ↓ RANGE 2
Tagged	#3 Poly manual vent valve top FLANGE LEAKING 300 ppm, 0850, already hosed
Tagged	VSP-5 on #6 Poly leaking at packing, 7100,000 ppm, 0900, hosed, this LEAK CAUSED SEVERAL small readings in the Poly area during shift, Forman had packing tightened & it was OK. 1015
—	Forman drain liquid out of HE-3N, 700ppm told forman the closed valve NUMBER OF RADIO PAGE CALLS TO INVESTIGATE A ALARM 1

ANK FLRM

TAG	NO ALARMS REPORTED OR NEW LEAKS FOUND
NO. OF PAGE CALLS TO INVESTIGATE A ALARM	NONE