


October 30, 1979

To: Holders of MDP Binders

From: J. V. Flynn, Adm. Bldg.



REVISION TO MECHANICAL DEPARTMENT PROCEDURE MDP-60
ASBESTOS CONTROL

Attached is a revised copy of MDP-60 - ASBESTOS CONTROL. Please destroy the copy now in your binder and insert the WHITE copy in its place. Paragraphs revised and an explanation for same are noted below.

If a GREEN copy is attached, please circulate through your group and then either destroy or let someone keep it if they so desire.

These changes should be reviewed with all concerned personnel.

Please note that the title is changed.

3. SOURCE OF EXPOSURE

- A. Change - Expanded possible source of asbestos fiber exposure based on actual experience.
- B. Change - Included used brake linings.

6. CONTROL OF ASBESTOS DUST

- F. Change - Added the word "asbestos" to the caution tag description.

9. SAMPLING

- B. (2) (3) (4) - Change and new item added - Clarification of sample gathering and routing procedure. Added new item on identifying of lines and equipment bearing asbestos materials.
- C. New - Describes procedure for dismantlement inventory of "white goods".
- D. Change - All air sample requests must be handled through the Mechanical Health and Environmental Coordinator.

DUP 0905739

121401

SC-DP-06130