

GRACE

Construction Products Division

May 30, 1986

PLAINTIFF'S
EXHIBIT
WRG-804

CPD ENC

TO: R. C. Deskin

SUBJECT: Insulation Material
in Machine Shop

FROM: C. W. Forrest

CC: F. W. Eaton

The T. R. Fabrication Machine Shop was chosen some years ago to be the test site for a M.K. type spray on insulation system being developed by our company. The walls and roof of the machine shop were sprayed with this material. Over the years, we have experienced the problem of this material loosening and falling into the work place. Also, the material on the walls has absorbed oils and greases from the machining operation which has caused a fire hazard.

To retain the falling material and improve the comfort of the machine shop personnel, the roof was covered with a paper covered E.P.S. Board (R-Barrier) in 1979/80. Soon afterward, this material began to separate and the paper now hangs down in stalagmite fashion from the roof.

In order to correct this condition and improve the general appearance and safety of the work place, this material should be removed and disposed of.

The enclosed photographs show not only patches of bare walls but sprayed material ready to fall and material laying on the floor. Photos were also taken of R-Barrier paper hanging from the roof. If you need additional information, please let me know.




C. W. Forrest

CWF:ml

Encl.

R000853?



INSULATION CO.

Contractors and Distributors

DIVISION OF NATIONAL SERVICE

1000 BERRY STREET • P.O. BOX 370 • NANTUCKET, MASSACHUSETTS 02546

June 19, 1986

W.R. Grace & Co.
P.O. Box 967
Travelers Rest, S.C. 29690

Attn: Mr. Charlie Forrest

Dear Mr. Forrest:

We propose to remove the sprayed on asbestos material from the shop area for the sum of \$18,800.00.

This project will take approximately 15 working days.

Our price is based on the owner furnishing water and electrical power.

All E.P.A. & O.S.H.A. regulations will be strictly followed.

If we can be of any further service please call.

Very truly yours,

SOUTH INSULATION CO.


J.M. Bradley
Manager

JMB:gul

R000854