

INTER-OFFICE MEMORANDUM



To: P. H. Stumpf

From: S. D. Sunski

Date: August 9, 1967

Subject: E. J. Bartells Complaint - Log No. 757

Evaluation:

Code No. 62159

001654

They list this manufactured material as poor and lacking binders.

Observation of the material shows a very soft fiber with too much dedusting agent applied. These factors cause the material to be ground up small and have no internal bond when sprayed.

Their claim that the material lacked binders was not entirely justified. When too much dedusting agent is applied the binders are locked in and are no longer visible. The fiber also becomes water repellent and will not lock together; adhesive in this case is no help.

SDS/ec

cc:

R. E. Schlemmer

G. R. Wolfe

Complaint log


SDS