

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/30/2024	Time	12:10
Inspection Due	2021-12-01T00:00:00Z	Operator Representative	White Palace Energy, LLC		
Operator Info	White Palace Energy, LLC 16210 Wind Hill Circle Skiatook, OK 74070 Phone: 918-396-7396	Inventory ID	OS5620000		
		API Well No			
		Lease Name	STUART UNIT		
		Well ID	64		
Location	NW 32 23N 11E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.431492	Longitude	-96.152962		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	White Palace Energy, LLC		
Inspect No.		Date Last MIT	07/22/2009	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 625
FLM Canister Pressure		Actual Pressure			Max Volume 10500
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector was unable to observe the fluid level due to lack of proper fittings to connect the Echometer. At the time of the inspection the well was disconnected and not injecting. There was no tubing or packer installed in the well. The well sign was not updated to reflect the current operator. The well was overdue for MIT.				
Inspector Signature					
Supervisor Signature (acting)					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.431492, -96.152962		
City: Avant	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010269

Orientation: W

Date of Photo: 01/30/2024

Time of Photo: 12:08 PM

Latitude: 36.431492

Longitude: -96.152962

Photographer: Matthew Allen

Description: This was well OS5620000 at the time of the inspection. The well was not equipped with proper fittings to allow observance of the fluid level. The well sign was not present.