

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	11/07/2019	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	LBOC, LLC	
Facility Name:	Staples-Olvey-Lion SWD	
Facility Physical Location:	33.318213, -92.516308	
(city, state, zip code)	Calion, Arkansas 71724	
Mailing address:	787 Baugh St.	
(city, state, zip code)	Norphlet, Arkansas 71759	
County/Parish:	Union County	
Facility Phone Number	870-546-3457	
Facility Contact:	Charles Long	
	longbrosoil@yahoo.com	
FRS Number:	N/A	
Identification/Permit Number:	ARU001230	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		12 DEC 2019
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the LBOC, LLC oil and gas facility located at latitude 33.318213 and longitude -92.516308 near Calion, Arkansas on 11/07/2019 for an unannounced inspection. There were no representatives of LBOC, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the Staples-Olvey-Lion Lease and is the site of an injection well.

Section II - OBSERVATIONS

I observed that a large amount of dirt work was being conducted on the back side on a large pit at the site. I observed that there had been a seep from the pit that appeared to have been stopped prior to the inspection. I observed that the secondary containment pit was 1/2 full of fluids and had oil on the surface of those fluids. I did not witness the injection well operating at the time of the inspection.

Section III – AREAS OF CONCERN

The secondary containment pit had fluids in it and a recent leak had been stopped, but remedial activities were still underway.

Section IV – FOLLOW UP

EPA water enforcement will conduct a follow up inspection in approximately 6 months.

Section V – LIST OF APPENDICES

N/A