

guidelines or regulations of the responsible state agency, EPA and OSHA.

- b. The contractor shall furnish proof that employees have had instruction on the dangers of asbestos exposure, on respirator use, decontamination, and OSHA regulations.

3. Worker's Dress and Equipment for Asbestos Removal

- a. Work clothes will consist of full body coveralls, disposable head covers, boots, or sneakers, and respiratory protective equipment as required by OSHA regulations. Eye protection and hard hats should be available as appropriate.

- b. Coveralls should be of a paper disposable type.

- c. Respiratory protection for workers shall be provided by the contractor as required by current OSHA regulation.

3. Decontamination

All workers, without exception:

- a. Will change work clothes at designated areas prior to start of day's work. Lockers or acceptable substitutes will be provided by the contractor for street and work clothes.

- b. All work clothes will be removed in the work area prior to departure from this area. Workers would then proceed to showers. Workers will shower before lunch and at the end of each day's work. Hot water, towels, soap, and hygienic conditions are the responsibility of the contractor.