

72
Nothing w/ broken
Decided to go with
Plan #2.

FILE
ASBESTOS

POSSIBLE ACTIONS TO TAKE ON ASBESTOS REPORT

1. Request Industrial Hygiene to test a few of the positive samples to determine what percent of asbestos does the dust contain. Plan action after receipt of report. Estimated cost per sample - \$50.00.
2. Request Industrial Hygiene to test all the positive samples if we believe the problem is severe, to determine what percent of asbestos does the dust contain - plan action after receipt of report. Estimated cost of test - \$650.00.
3. Issue order to tradesmen removing all ceiling tile to wear approved respirators, wear protective clothing and follow instructions in February 27, 1981 Safety Broadcast Bulletin on Asbestos - Recommended Work Practices. Do not request further test and follow work practices as if all ceiling dust contains asbestos.
4. Start a cleaning program on ceiling areas that had a positive test. This may not be a good program because if the dust was contaminated from asbestos insulation above the area, in time it could become contaminated again.
5. Place a monitor on one of our tradesman and have him remove ceiling tile in the thirteen locations and test to determine if tradesmen are exposed to asbestos performing this work. Plan action after receipt of report.

J. W. Woodward

J. W. Woodward
March 17, 1981

PLAINTIFF'S
EXHIBIT
WV-06315

PLAINTIFF'S
EXHIBIT
316510

SCF-ALLF-08490

PIPPINS V FORD
83-11-00 37- 39