

NR111
WAD 000105
383
Adm
Control
m.s.c.
PB
430.1
430.2
430.3

14 FEBRUARY 1978 1928

FROM: PRODUCTION OFFICER

TO: ALL GROUP SUPERINTENDENTS
ALL SHOP SUPERINTENDENTS

SUBJ: ASBESTOS

REF: (A) NAVSEA MESSAGE 061928Z OF FEBRUARY 1978

1. NAVSEA VIA REFERENCE (A) RECOMMENDED CONTROLS FOR WORKING ASBESTOS CONTAINING GASKETS.

2. THE FOLLOWING CONTROLS WILL BE USED UNLESS INDIVIDUAL OPERATIONS HAVE BEEN EVALUATED BY THE INDUSTRIAL HYGIENE BRANCH AND MORE STRINGENT CONTROLS HAVE BEEN IMPLEMENTED. SHOP PERSONNEL SHALL COMPLY WITH THE FOLLOWING REQUIREMENTS FOR ASBESTOS GASKET WORK.

A. MULTIPLE (MORE THAN 5 GASKETS) MACHINE OPERATIONS WORKING ASBESTOS GASKET MATERIALS REQUIRE AIR-SUPPLIED RESPIRATORS WHEN THE MACHINE IS NOT EQUIPPED WITH AN ASBESTOS VACUUM CLEANER.

B. MULTIPLE (MORE THAN 5 GASKETS) HAND OPERATIONS WORKING ASBESTOS GASKET MATERIALS REQUIRE AIR-SUPPLIED RESPIRATORS.

C. MULTIPLE (MORE THAN 5 GASKET) MACHINE OPERATIONS WORKING ASBESTOS GASKET MATERIALS REQUIRE A NIOSH APPROVED DUST RESPIRATOR WHEN THE MACHINE IS EQUIPPED WITH AN ASBESTOS VACUUM CLEANER.

D. LESS THAN 5 HAND OPERATIONS WORKING ASBESTOS GASKET MATERIAL REQUIRE A NIOSH APPROVED DUST RESPIRATOR.

E. ASBESTOS GASKET INSTALLATION AND REMOVAL REQUIRE DUST RESPIRATORS.

F. FLANGE CLEAN-UP (SCRAPING, BRUSHING, ETC.) AFTER ASBESTOS GASKET REMOVAL REQUIRES DUST RESPIRATORS.

G. ALL SCRAP AND WASTE MATERIALS WILL BE CONSIDERED AS ASBESTOS AND SHALL BE HANDLED IN ACCORDANCE WITH NAVSHIPYD PUGET INSTRUCTION C252.11, PART B, CHAPTER 1.

0000093

3. THE ABOVE CONTROLS SHALL BE EXERCISED FOR THE FOLLOWING MATERIALS:

FED. STX NO.	AVAILABLE AT CHSP STORES	TRADE NAME
5532-10-545-0501	CS AND 56	CARLOCK
5532-10-545-5502	58	JOHN MARVILLE CARLOCK CORSCO
5532-10-545-4727	58	JOHN MARVILLE CARLOCK
5532-10-545-4723	58	JOHN MARVILLE CARLOCK FICOLET INC.
	41 AND 56	CARLOCK

U. S. DEPT
OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C. 20535

3-10-68, 3-10-68, 3-10-68, 3-10-68
3-10-68, 3-10-68, 3-10-68, 3-10-68

0000000