

Young 12-8-8 12/21/78
 OVA CALIBRATION 1.0 BACKGROUND 5PPM OVA NO. I
 PERMIT TO ENTER BUILDING 121 WITH OVA. FOREMAN Jamison TIME 12:45
 PERMIT TO ENTER LPA AND TANK FARM WITH OVA. FOREMAN Jerry TIME 1:25

BLDG. 121

POINT	RESULTS OF INVESTIGATING CAUSE FOR ALARMS OVER 3 PPM
8	Bldg incoming ventilation; >1ppm alarm - checked roof for source; due to other pits started to show increase in readings - no source found;
5.6	#30 poly - charging line above charging valve @ small sight glass - leaking @ black gasket above sight glass. - blowing across Bldg to pit, hose, leak reading dropping slowly.
NUMBER OF RADIO PAGE CALLS TO INVESTIGATE A ALARM (11)	

SOURCE OF EMISSION	Tag No.	GC PPM	OVA PPM	Time Found	Person Notified	Action Taken
#46 poly manhead opening 5K - must hose in poly	-	71	150	0100	OPER	Hosed
#47 poly Rupture disc leaks @ flange	AT	71	1000	0050	OPER	TAGGED
#38 poly center rotator blank flange emitting fumes @ gasket	2186	71	2000	0055	Furnisher	TAGGED HOSED
#27 poly ORING LEAKS @ GASKET	2187	71	400	0100	Furnisher	TAGGED - HOSED
#30 poly charging line leaks @ sight glass	2190	73	100000	0620	Furnisher	

LARGE POLY AREA

TAG	
	No Alarms Reported.
	No leaks found in Area
NUMBER OF RADIO PAGE CALLS TO INVESTIGATE A ALARM 0	

TANK FARM

TAG	
	No Alarms Reported
NO. OF PAGE CALLS TO INVESTIGATE A ALARM 0	