

ABD00344808

CONOCO CHEMICALS — ABERDEEN PVC PLANT DOSIMETRY CARD (A)


SAMPLE No 0048

Hazard: VCM (X) Lead () Noise () _____ () Date 10/20/79

Name Larry Frye S.S. # 416-74-1049 Shift C

Department Vinyl L. R. Job Class Chief Operator

Instrument No. 116	Start Time 6:52 AM	Stop Time 7:02 PM (X)
Noise Cell No. _____	Airflow _____	

Analyst:  Analysis Date: 10-24-79

Hazard	TWA Exposure	
VCM	PEL: 1 PPM	0.1 PPM
Noise	Over () Under () 115 dBA	% of PEL
Lead (Micrograms)	TOT: _____ PEL: _____ Per M ³	Per M ³

CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)

SAMPLE No 0048

Hazard: VCM (X) Lead () Noise () _____ () Date 10/20/79

Time Clock (Lead Sampling Only) : IN: 0700 AM (✓) PM () OUT: 1900 AM () PM (✓)

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
Rx area	6 hr	Bagging area	2 hr
Dryer area	2 hr		

List most likely causes of possible overexposure to the hazard.

1. Rx area
- 2.
- 3.

Check respiratory protection you used:

(✓) None () Dust Mask () Air-line Respirator () Scott Air-pak

Signature

Harry Frye

Please complete and return to guard