

MATERIAL SAFETY DATA SHEET

S-3375-1

SECTION I

MANUFACTURER'S NAME

Raybestos-Manhattan, Inc.

EMERGENCY TELEPHONE NO.

203/371-0101

ADDRESS (Number, Street, City, State, and ZIP Code)

100 Oakview Drive, Trumbull, Connecticut 06611

CHEMICAL NAME AND SYNONYMS

None

TRADE NAME AND SYNONYMS

S-3375-1

CHEMICAL FAMILY

Molded Brake Lining

FORMULA

SECTION II - HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS Litharge	4-8	
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)
Asbestos: Max. 2 fibers 5 microns/cm ³ is TWA limit of exposure and maximum level of 10 fibers instantaneous reading				45-55	
Litharge: TLV = 50 micrograms/m ³ on 8 hr. TWS					
OSHA Lead Standard #1910.1025					

SECTION III - PHYSICAL DATA

BOILING POINT (°F.)	NA	SPECIFIC GRAVITY (H ₂ O=1)	1.96
VAPOR PRESSURE (mm Hg.)	NA	PERCENT VOLATILE BY VOLUME (%)	NA
VAPOR DENSITY (AIR=1)	NA	EVAPORATION RATE (_____=1)	NA
SOLUBILITY IN WATER	Negligible		
APPEARANCE AND ODOR	Gray, rigid, slight rubber odor		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used)	NA	FLAMMABLE LIMITS	Let	Uet
EXTINGUISHING MEDIA	CO ₂			
SPECIAL FIRE FIGHTING PROCEDURES	None			
UNUSUAL FIRE AND EXPLOSION HAZARDS	None			

PAGE (1)

(Continued on reverse side)

FILED - Bayonne, N. J.

PLAINTIFF'S
EXHIBIT

WV-021597

PLAINTIFF'S
EXHIBIT

78702.01

GEWVOCT04-011589

WV-21597

SECTION V - HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE	See section II
EFFECTS OF OVEREXPOSURE	Chronic - Asbestosis and Cancer Those associated with lead.
EMERGENCY AND FIRST AID PROCEDURES	NA

SECTION VI - REACTIVITY DATA			
STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	XX	
INCOMPATIBILITY (Materials to avoid)			
HAZARDOUS DECOMPOSITION PRODUCTS			
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII - SPILL OR LEAK PROCEDURES	
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	
Vacuum or wet cleaning if dust involved.	
WASTE DISPOSAL METHOD	
Sealed containers properly labelled as specified in 29CFR1910.1001.	

SECTION VIII - SPECIAL PROTECTION INFORMATION		
RESPIRATORY PROTECTION (Specify type) NIOSH approved respirator for lead dust and asbestos fiber - See 1910.134		
VENTILATION	LOCAL EXHAUST	SPECIAL
	MECHANICAL (General)	OTHER
PROTECTIVE GLOVES		EYE PROTECTION
OTHER PROTECTIVE EQUIPMENT Depends on usage (See 1910.1001)		

SECTION IX - SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	
Proper labels required. 1910.001	
OTHER PRECAUTIONS	