


PERMIT NO. NPDES - LA-0000761 (NON-COMPLIANCE REPORT)

Monitoring Period: 4/18-24/82

Date: April 30, 1982

Event com o.	Effluent Characteristic	Lbs./Day Discharge Limitation	Lbs./Day Effluent Deviation	Date of Deviation	Time of Deviation	Reason or Explanation
18/118	TOC	2600	+364	4/22		The exact cause of the violation has not yet been determined. A diligent effort is underway by Operations and Process personnel to identify and correct the source of this and previous TOC excursions. Insufficient bleach addition and other operational parameters are being examined closely for some type of correlation with high TOC levels.
1/017/ 019	TSS	2236	+141	4/23		Due to a reduced demand for product; idled chlorine circuits have caused an increased flow to the Lead Treatment ponds, thereby reducing the retention time allowed for sedimentation of suspended solids. Subsequent to this sample, the flow has been decreased by bringing another chlorine circuit on stream.
						
						I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate, and complete and I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

SL 045669

[illegible]

[illegible]

SL 045671

110 HIGGINS, INC., BANK CHIEFS, BR

Reporting Period: 3/28 - 4/3/82

DATE: 4/8/82

[illegible]

SI. 045672