



Mr. C. Frankenger
Linde Division
Speedway Factory
4801 West 16th Street
Indianapolis, Indiana 46224

August 22, 1975

Medical Department

4

Mr. P. J. Burtis
Mr. S. E. Hine
Mr. H. L. Phillips
Mr. L. J. Suelter/Mr. R. P. Wooldridge
Mr. R. M. Neary/Mr. B. Higdon
Dr. J. J. Welsh/Dr. K. S. Lane

Dear Mr. Frankenger:

A special industrial hygiene survey was made on August 13, 1975 to follow up on the asbestos in air problems associated with the acetylene cylinder manufacturing operations. The series of samples obtained during the second quarter indicated an increase in the number of air-borne fibers at certain locations. It has been determined that part of the reason for this was the switch to loosely bagged material because of supply difficulties in obtaining the usual compacted asbestos.

Of all the recently collected samples and those obtained on this visit the only ones above the limit are those collected at the shredder location.

The results were as follows:

Location	Asbestos Fibers per ml > 5 microns	Remarks
Machine shop-cutting cylinder open	1	8/6 personnel sampler

A21673

UCC 009380

PLAINTIFF'S EXHIBIT

UC-4279



Mr. C. Frankenger

-2-

August 22, 1975

Location	Asbestos Fibers per ml > 5 microns	Remarks
Maintainence shop-cutting filler samples	2	8/6 personnel sampler
Lance out room - general	< 1	7/25 normal operations
Shredder room-personnel sampler	9	7/25 Blower operating*
Shredder room-general area	10	8/1 visible dust
Top of asbestos mix tank-general	< 1	7/29 Blower in operation
Valve well drilling-personnel sampler	< 1	8/8 2 skids of B's
Top clearance inspection station	< 1	8/12 personnel sampler
General area Dept. 511	1	8/13, 9 a.m. usual operations
General area Dept. 511	< 1	8/13, 10 a.m. usual activity
Top of Power Cabinet-general air	< 1	8/13, 9:40 a.m.
Asbestos Storage area-warehouse	< 1	8/13 no activity
Shredder room-general	1	8/13 towards end of clean-up
Shredder room-general	6	8/13 while dumping bags
Shredder room - personnel sampler	9	8/13 as above*

*It was noted on both sampling periods in the shredder room that the operator climbed inside the shredder twice in order to dislodge stuck parts of the bales of asbestos. He was wearing a respirator while performing this

A21674



Mr. C. Frankenger

-3-

August 22, 1975

job. It is felt however that this situation could be improved so that it does not require a person to enter the shredder,

Better control in the shredder room is necessary since the levels found either approach or are at the ceiling limit of 10 fibers per ml.

Other areas in the plant were investigated as time permitted and various conditions discussed with Mr. Hine and others.

Certain welding and brazing operations were observed and it was suggested that personnel type samples be obtained where cadmium and silver are major constituents. These samples may be forwarded to me so that analytical results may be obtained. Similar type samples should be obtained where lead is a major constituent so that exposure evaluation may be made. Results of these samples would then become part of an exposure record for the various operations throughout the plant.

If you have any questions, please let me know.

Very truly yours,

Leo J. LaFrance
Industrial Hygienist

LJL:lm

A21675



INTERNAL CORRESPONDENCE

LINDE DIVISION

• SPEEDWAY FACTORY

4801 WEST 18th STREET, BOX 3800, ST. LOUIS, MISSOURI 63108

To (Name)	Mr. L. J. LaFrance	Date	August 12, 1975
Division	Linde Division	Originating Dept.	Quality Assurance
Location	Medical Dept., 4th Floor New York, New York 10017	Answering letter date	
Copy to	Mr. S. E. Hine Mr. L. G. Snelter	Subject	Air Samples, 3rd Quarter

Eleven (11) air samples were taken for the third quarter of 1975 at various locations throughout the Acetylene Cylinder Operations. The attached summary outlines the locations and other pertinent data. If you have any questions, please call.

R. P. Woolbridge
R. P. Woolbridge

RPM:nj
attachment

421876

2358840 Q95 :H210M

2591 : 9A3Y

МОНИТУНГЪ НА СЪПРЕЗ

[illegible]

EXP. DATE: 10/8/01

8-13-72

