


Figure 4. Steps in investigating for the presence of asbestos.



\*Negative certification is a statement certifying that no friable asbestos is present.