

PLANT MANAGER'S SAFETY BOARD

cc: P. Brubaker
G. Small

MINUTES OF MEETING

December 20, 1978

PLAINTIFF'S EXHIBIT

MON-791

Present:

G. W. Bostick
J. E. Clark
G. A. Danner
G. W. Daues
W. C. Fuller
J. A. GlassR. C. Martini
M. L. Owens
W. L. Riddick (for McCullough)
D. W. Metten
G. T. Ryan
J. G. Trafton
W. H. Triplett1. REVIEW OF STATISTICS

TEXAS CITY SAFETY PERFORMANCE SUMMARY

November 1978

TOTAL INJURY CASES

1977		1978	
MTD	YTD	MTD	YTD
33	279	18	274

RECORDABLE CASES

	1977		1978	
	MTD	YTD	MTD	YTD
(a) INJURIES WITHOUT LOST WORK-DAYS (medical treatment only)	4	29	3	27
(b) LOST WORKDAYS CASES	0	8	0	6
**B ₁ RESTRICTED ACTIVITY	0	4	0	3
**B ₂ DAYS AWAY FROM WORK CASES	0	4	0	3
(c) FATALITIES	5	6	0	0
*TOTAL RECORDABLE CASES	9	43	3	33
*A+B+C = TOTAL RECORDABLE INJURIES				
**B ₁ + B ₂ = (B) TOTAL LOST WORKDAY CASES				

INJURY RATES PER 200,000 MANHOURS

	1977		1978		NOVEMBER YTD 1978 MCIC
	MTD	YTD	MTD	YTD	
TIR - TOTAL INJURY RATE	24.21	17.91	13.37	17.25	
RIR - RECORDABLE INJURY RATE	6.60	2.76	2.23	2.08	2.16
TLWR - TOTAL LOST WORKDAY CASE RATE	0	0.51	0	0.38	.70
DAWR - DAYS AWAY FROM WORK CASE RATE	0	0.26	0	0.19	.33

TLWR TARGET: 1.45 (1/2 CHEM. IND. AVG.)

STG 2430873

SC

14028

LAM015817

2. COMMENTS ON STATISTICS

In addition to the statistics, it was pointed out that there was a rising trend in Chemical Contact, Lifting/Pushing/Pulling, and in Striking Against categories.

3. OLD BUSINESS

a. Emergency Procedure Manuals -- Glass

The revisions in the Emergency Procedure Manuals are virtually complete with the exception of a few sections that were in for typing and printing.

b. Plant-Wide Alarm System Survey -- Triplett

Results of the plant-wide safety alarm survey shows certain parts of the plant needing improvement. Engineering work orders have been requested to bring these areas up to standard.

A recheck of the plant-wide alarm system will be made during the January test of the Emergency Procedure plan.

Some concern had been expressed by a number of groups in the plant about the cyanide area alarms and how they are tested. These new area alarms are being installed and are expected to be ready for testing at the time of the next Plant Emergency Procedure Test. Plant-wide publicity will be given to the cyanide alarms, what they indicate, and actions to be taken when they are sounded.

c. Respiratory Protection on Fit Testing -- Ryan

The Procedure Bulletin for Respiratory Protection Procedures has been completed and most of the comments have been resolved. The SAC plans to review it in detail with Mike McCullough prior to releasing it to final typing for issue. Also included are plans for plant-wide publicity and training prior to implementing this new procedure.

d. 1978 Property Protection Survey -- Glass

The report of the 1978 S&PP Survey contained a number of positive comments about the overall safety program and its effectiveness. Certain areas for improvement were identified. The report of the S&PP Survey will be sent to members of the PMSB.

4. REPORT OF THE SAFETY ADVISORY COMMITTEE (SAC) -- G. T. Ryan

The remaining items on the SAC committee agenda include the following:

1. A request for revision of the rules regarding riding bicycles through operating units.

2. S&PP Tech-Facts, No. 31, dealing with the control of water treatment processes.
 3. Lighting inside tanks and vessels
 4. Tank content signs
5. REPORT OF SAFETY AND HOUSEKEEPING ACTION COMMITTEE (SHAC) -- TRIPLETT

The Hourly Safety Committee's plans, programs, and progress were reviewed.

A question of "How well we are following the Fire Entry Permit Procedures?" was raised by the Hourly Committee. A detailed review of the procedure revealed that there was room for confusion about the intent of the authors; therefore, the SHAC is reviewing it with the authors to clarify some of the wording. It is expected that the Fire & Entry Permit Procedure will be rewritten.

Activities Status Report: This quarterly report of the SAC has been issued. Also remaining on the agenda is the Plant Breathing Analyzer and the Procedure for the use of hoses within the plant. Recommendations for these two items are expected to reach SAC in January.

6. REVIEW OF INCIDENTS

Major Injury to a Pipefitter in Dept. 13 - A pipefitter was injured on the tips of second and third finger of his left hand when a high-pressure water cleaning "Mole" was withdrawn from a pipe run. The physician found no water penetration in either cut and returned the pipefitter to full duty; however the investigation indicated that a much more serious injury might have resulted if it had not been for the prompt and alert action of the other Mole crew members.

The primary cause was the complacency on the part of the injured after making hundreds of runs in and out of pipes with the cleaning device. A contributing cause was the low visibility of the tape marking the hose which shows how far to retract the mole before shutting down the pressure. Review of the cause with the injured and other craftsmen trained to use this tool is in progress. Corrective actions regarding the rotation of the person doing this work and proper marking of the hose is in progress.

7. OTHER SIGNIFICANT EVENTS

- 1) Decatur Fire: A major fire occurred at Decatur when an AN pump ruptured due to vibration. The fire was under a pipe rack and was so intense that a high-pressure steam header failed and caused a one-week shutdown of the plant. Details of this fire are expected to be circulated at Texas City when the report of the fire is issued by Decatur.

SC

14030

STG 2430875

LAM015819

- 2) An incident occurred at Seal Sands in which the high-pressure reducing valve on a steam line failed due to sonic vibration. Details of this failure will be made available when the report is received from Seal Sands.

8. CONTRACTOR SAFETY -- BILL RIDDICK

Riddick reported that following the AN shutdown, a meeting was held with Opel Management regarding safety performance which resulted with a significant improvement during the styrene, acetic acid, and methanol shutdowns. This good safety performance was continuing at the time of the PMSB meeting.

9. OTHER ITEMS

- A. An operator received an exposure to TBA vapors when opening a tank truck hatch shortly after a transfer to the tank had been made. This was considered a Recordable Case because the operator developed chemical bronchitis and was given prescription medicine to relieve the condition but was returned to work without loss of time.
- B. Metten will review the procedures to determine what might be done to remove unneeded pipes from the pipe racks as a part of revision or modification projects in which retirement of capital assets is involved.
- C. The CED Site Safety Survey was held December 14 and 15, 1978.


J. A. Glass

JAG/jge

1/12/79

SC

14031

STG 2430876

LAM015820