

Monsanto

GTR

FROM (NAME & LOCATION) G. T. Ryan - Texas City

DATE September 5, 1978

CC:

SUBJECT SAC Meeting Agenda

REFERENCE Thursday, September 7
10:00-12:00 noon

TO :
J. G. Trafton
D. W. Metten

PLAINTIFF'S EXHIBIT

MON-2595

- 1) Review "Hose Inspection Procedure" submitted by SHAC (copy attached).
- 2) Review Revised P-0112, "Injury, Illness & Near-Miss Investigation & Reporting." (Copies issued last meeting).
- 3) Review "Respiratory Protection Procedure on Fit Testing and Beards." (P-0130). Brubaker and Clark can meet with us as needed (copy attached).
- 4) Follow up on Purple Peeper plans from August 10 SAC meeting.

Row 106

G. T. Ryan

/ob
Enclosures

SC

15416

LAM025168

PLANT MANAGER

POLICY

PLANT MANAGER'S
SAFETY BOARD

SAFETY ADVISORY COMMITTEE

RECOMMEND

SAFETY & HOUSEKEEPING
ACTION COMMITTEE

ACTIONS
PROGRAMS
PROCEDURES

UNIT/CRAFT
SAFETY
PROMOTION
TEAMS

33 GROUPS
150 PEOPLE

SUPV/HOURLY
OPN'S/MAINT

HOURLY
SAFETY
COMMITTEE

9 MEMBERS

PLANTWIDE
HOURLY
INPUT

PROCESS
TECHNOLOGY
COMMITTEE

4 MEMBERS

LABS AND
BENCH UNITS

OFFICE
SAFETY
COMMITTEE

9 MEMBERS

OFFICE
WORKERS

✓ See above Page 6 (3) Close off the unit premises by covering with the bottom of the hand.
✓ PEB "Looks good to me."

✓ Patricia/HLP Plank

✓ Willock Page 6 The new test permanent standard as interpreted by LP & S requires a quantitative fit test. It is understood he would purchase a test unit and begin to use it.
Reading it - not to worry - P. will read.

✓ Xuller Page 3 A(1) Inspect the work areas (in conjunction with LP & S) to evaluate. ---
He would delete bracketed line.

Page 4 B(1) Work with operating unit and craft supervision (when requested) in the inspection of work areas. ---
He would add bracketed line.

(H6 to delete)

Thanks to See attached comment. (Don't need it)

✓ TAM "Looks good"

✓ Phil Evans See attached comment.

✓ EGF II 3.4. (6) Page 5 "In case of an emergency the standby man should sound alarm but not begin rescue operations until he has confirmed help coming with rescue equipment also."

✓ Kalbfleiter See attached comment.

For his
info to
be
checked.

SC

15418

LAM025170

Only minor comments have been
made about incoming quality of breathing
air in the headers. There has been a problem
recently on moisture content - the air became
too dry; also some contaminants into the
air ^{passage} intake, wherever that is, could
enter the system undetected.

The policy on facial hair is a touchy
one. The way it is stated is fine. We were
asked by the area to have our technicians
shave their beards, even though they do not
wear air breathing masks. There were no
problems, but that situation is not covered. Ph