

TABLE I
VCM OVEREXPOSURES FOR JUNE, 1980

<u>Date</u>	<u>Job Classification</u>	<u>8-Hour TWA Overexposure, ppm</u>	<u>Cause</u>
6/10/80	Maintenance Mechanic	1.1	Specific cause not determined. Worked in old vinyl reactor area. Did not wear respirator
6/18/80	Maintenance Mechanic	1.3	Worked on 744 reactor and VCM recovery receiver in new vinyl reactor area. Wore an air-line respirator.
6/28/80	Vinyl Shift Supervisor	4.2	Specific cause not determined. Worked in new vinyl reactor area. Did not wear respirator.
6/30/80	Maintenance Supervisor	1.6	Worked on inerts removal refrigeration unit in old vinyl reactor area. Did not wear respirator.