

Contractors should be encouraged to receive training to train their workers in safe work practices and in proper removal, encapsulation, and enclosure methods. Contractor and worker training can be required in the contract.

1. Regulations

Contractors shall comply with the requirements of the EPA regulations, National Emission Standards for Asbestos, and the OSHA regulations on asbestos, Section 1910.1001 [and any applicable State and local government regulations] which are incorporated by reference.

2. Scope of Work

A. The Contractor shall furnish all labor, materials, services, insurance, and equipment necessary to carry out the [removal operation, encapsulation operation] in accordance with the EPA and OSHA regulations [and any applicable State and local government regulations].

B. The Contractor shall be responsible for obtaining approval for a waste disposal site in compliance with Section 61.25 of the EPA regulations.

C. Contractors shall post the EPA and OSHA regulations [and any applicable State and local government regulations] at the job site.

Worker Protection

A. The Contractor shall provide workers with approved respirators. The Contractor shall provide a sufficient quantity of filters approved for asbestos so that workers can change filters during the work day. Filters shall not be used any longer than one (1) work day. The respirator filters shall be stored at the job site in the change room and shall be totally protected from exposure to asbestos prior to their use.

B. Workers shall always wear a respirator properly fitted on the face in the work area.

C. Contractors shall instruct and train workers in proper respirator use.

D. Workers shall wear disposable, full-body coveralls and disposable head covers and footwear in the work area. Footwear may be disposable. Non-disposable footwear shall be left in the work area at all times until disposal at job completion.

E. The Contractor shall set up a change room and a shower outside of the work area.

F. All workers without exception shall:

(1) Remove street clothes in the change room and put on the disposable coveralls and head covers, and respirator before entering the work area.

(2) Remove the disposable coveralls, head covers, and footwear in the work area before leaving the work area. Still wearing their respirators, proceed to the showers and remove their respirators while showering with soap and water.

(3) Shower at the end of each day's work before entering the change room to change into street clothes.

G. Workers shall not eat, drink, smoke, chew gum, or chew tobacco in the work area. To eat, drink, or smoke, workers shall remove the disposable work clothes and footwear in the work area before leaving the work area. Still wearing their respirators, workers shall proceed to the showers and remove their respirators while showering with soap and water. Workmen shall then dress into a new, clean disposable coverall to eat, smoke, or drink. The new coverall can be worn to reenter the work area.

H. The Contractor shall provide a respirator and disposable coveralls, headcover, and footwear to any official representative of the school who inspects the job site.

I. All persons entering the work area shall wear an approved respirator and disposable coveralls, head cover, and footwear.



8006 0366

Worker Dressed in Protective Clothing