

Leo & Lew
This is important. Please give careful
attention!

sent 2/2/68

February 1, 1968

WJS

cc: S. M. Lillis

W. J. Sheehan

R. H. Bates

L. W. Winchester

C. M. Nielsen

V. J. Labrecque

J. F. Feldmann

R. T. Budovec

J. J. Rokos

TO: L. S. Dymitro

FROM: J. G. Belter

CUSTOMER: Caterpillar Tractor Company
Peoria, Illinois

REFERENCE: Ground VICTOCOR 300

Referring to S. M. Lillis's note to you dated January 19, 1968, attached please find a piece of ground VICTOCOR 300 material depicting the ground prongs.

I have examined this piece of material and have the following comments and questions:

L.S.D.

1. I removed the facing material from each side of the core and measured its thickness. The ground side appears to have approximately 50% less facing material left on the core than the unground side. I don't believe this should occur if the material is made per standard established.

L.S.D.

2. Is the clinch acceptable to our standards established in the development of this material.

V.J.L. & L.S.D.

3. Does this material meet our specification for VICTOCOR 300?

(a) Physical properties.

(b) Factory Standard for Manufacturing.

VPD-91-0003003